

ASS. REC. BY:

REF: C12/21010190/KV C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured: GBG 1070E

Policy No. DMCVSNW00115542100

Claims No. SNM21D205331/C04/LEEPG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

1-31 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/11/21

Kenneth confirmed \$13,292 (Red 5672.60, 30%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 17/11/21-typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ 13,292

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 806631

TEL : 6249 6118

FAX : *Return by 12/11*

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBG1070E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2018

ACCIDENT DATE : 19/09/2021

TP VEH REG NO : GBG1070E

ESTIMATE

NO : QUOT202110-000004(00)

DATE : 01/10/2021

POLICY NO : 999995580

VEH REG NO : SML6308G

MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)

CHASSIS NO : WDD2050402R470129

ENGINE NO : 27491031665902

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SML6308G

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Bootlid	1	2,405.00	2,405.00 ✓
2 Bootlid centre chrome	1	147.00	147.00 ✓
3 Bootlid weatherstrip	1	220.00	220.00 ✓
4 Bootlid centre logo	1	54.00	54.00 ✓
5 Bootlid 'C180' emblem	1	109.00	109.00 ✓
6 Bootlid '9G-TRONIC' emblem	1	128.00	128.00 ✓
7 Rear end panel	1	1,578.00	1,578.00 ✓
8 Taillamp panel - LH	1	180.00	180.00 ✓
9 Taillamp assy - LH	1	775.00	775.00 ✓
10 Rear fender - LH	1	2,560.00	2,560.00 ✓
11 Rear fender granish - LH	1	208.00	208.00 ✓
12 Rear fender inner trim - LH	1	325.00	325.00 ✓
13 Rear fender inner trim cover - LH	1	88.00	88.00 ✓
14 Rear bumper	1	1,805.00	1,805.00 ✓
15 Rear bumper reinforcement	1	740.00	740.00 ✓
16 Rear bumper side retainer - LH	1	65.00	65.00 ✓
17 Rear bumper lower spoiler	1	292.00	292.00 ✓
18 Rear bumper lower chrome	1	321.00	321.00 ✓
19 Rear bumper tow cover	1	59.00	59.00 ✓
20 Rear bumper sensor	1	195.00	195.00 ✓
21 Rear bumper sensor seals	4	12.00	48.00 ✓
22 Rear bumper clips	15	9.00	135.00 ✓
23 Rear bumper centre inner frame	1	105.00	105.00 ✓
24 Rear bumper bracket - LH	1	65.00	65.00 ✓
25 Rear fender inner shield - LH	1	208.00	208.00 ✓
26 Rear door - RH - LH	1	2,455.00	2,455.00 X
27 Rear door weatherstrip - LH	1	328.00	328.00 X
28 Rear door trimboard rivets - LH	20	9.00	180.00 X
			15,778.00
		Less 10%	1,577.80
			14,200.20
SPECIAL NET			
29 Rear windscreen sealant	1	60.00	60.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

R/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBG1070E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 19/09/2021

TP VEH REG NO : GBG1070E

ESTIMATE

NO : QUOT202110-000004(00)

DATE : 01/10/2021

POLICY NO : 999995580

VEH REG NO : SML6308G

MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)

CHASSIS NO : WDD2050402R470129

ENGINE NO : 27491031665902

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SML6308G

Description	Quantity	Unit Price	Amount
		S\$	S\$
LABOUR			60.00
30 To remove and refit rear windscreen glass	1	150.00	150.00 12cl
31 To remove and refit rear interior garnish and trimboard to facilitates the repairs	1	180.00	180.00 12cl
32 To transfer LH rear damaged door interior mechanism and glass to new door	1	150.00	150.00 X
33 To remove and refit rear bumper sensor	1	100.00	100.00 6cl
34 To check and rectify wiring system	1	80.00	80.00 2cl
35 To panel beat and straighten LH rear fender inner panel, LH rear chassis frame, to cut and weld rear end panel, LH rear taillamp panel, LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00 12cl
36 To putty and spray paint on affected areas	1	1,800.00	1,800.00 90cl
37 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00 9cl
			4,420.00
		TOTAL	S\$ 18,680.20
		ADD GST @ 7%	1,307.61
		GRAND TOTAL	S\$ 19,987.81

SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED EIGHTY-SEVEN AND CENTS EIGHTY-ONE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be submitted by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/09/2021 00:00 (SGT)
Date of Accident	19/09/2021 10:00 (SGT)
Exact Location of Accident	Near 3 Soon Lee St, Pioneer Junction, Singapore 627606
Additional Location Information	JUNCTION OF UPPER JURONG ROAD AND PIONEER ROAD NORTH
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML6308G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXXX78Z
Email Address	eugene.koh@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C180
Variant	AVG (R17 LED)
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595


INSURANCE COMPANY

Name of Insurance Company	AIIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

DRIVER


Name of Driver	HUANG JING
----------------	------------





Upper Tong Road

- A. SMLE208G
- B. GRG1070E
- C. GBC3114X
- D. SMY4426Y



Driver Road

Policyholder's Signature
Date & Time:

Hufy
Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Reporting Centre Personnel's Signature
Name:
NRIC/FN No.: