

REF: C72/21010190/KV



TONG LUCK AUTO PTE LTD
 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
 Tel: 6250 0088 Fax: 6250 5545
 Email: operation@tlauto.com.sg
 GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
 1 GATEWAY DRIVE
 #15-08 WESTGATE TOWER
 SINGAPORE 608531
 TEL : 6849 8118
 ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202110-000004(00)
 DATE : 01/10/2021
 POLICY NO : 999995580
 VEH REG NO : SML6308G
 MAKE/MODEL : MERCEDES BENZ C180 AVG
 (R17 LED)
 CHASSIS NO : WDD2050402R470129
 ENGINE NO : 27491031665902
 REG. DATE : 2018

YOUR REF NO : GBG1070E
 CLAIM TYPE : THIRD PARTY
 TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 ACCIDENT DATE : 19/09/2021
 TP VEH REG NO : GBG1070E

Estimate Repair Cost to Vehicle No : SML6308G

Description	Quantity	Unit Price	Amount
NET PRICE		S\$	S\$
1 Bootlid	1	2,405.00	2,405.00
2 Bootlid centre chrome	1	147.00	147.00
3 Bootlid weatherstrip	1	220.00	220.00
4 Bootlid centre logo	1	54.00	54.00
5 Bootlid 'C180' emblem	1	109.00	109.00
6 Bootlid '9G-TRONIC' emblem	1	128.00	128.00
7 Rear end panel	1	1,578.00	1,578.00
8 Taillamp panel - LH	1	180.00	180.00
9 Taillamp assy - LH	1	775.00	775.00
10 Rear fender - LH	1	2,560.00	2,560.00
11 Rear fender granish - LH	1	208.00	208.00
12 Rear fender inner trim - LH	1	325.00	325.00
13 Rear fender inner trim cover - LH	1	88.00	88.00
14 Rear bumper	1	1,805.00	1,805.00
15 Rear bumper reinforcement	1	740.00	740.00
16 Rear bumper side retainer - LH	1	65.00	65.00
17 Rear bumper lower spoiler	1	292.00	292.00
18 Rear bumper lower chrome	1	321.00	321.00
19 Rear bumper tow cover	1	59.00	59.00
20 Rear bumper sensor	1	195.00	195.00
21 Rear bumper sensor seals	4	12.00	48.00
22 Rear bumper clips	15	9.00	135.00
23 Rear bumper centre inner frame	1	105.00	105.00
24 Rear bumper bracket - LH	1	65.00	65.00
25 Rear fender inner shield - LH	1	208.00	208.00
26 Rear door - RH - LH	1	2,455.00	2,455.00
27 Rear door weatherstrip - LH	1	328.00	328.00
28 Rear door trimboard rivets - LH	20	9.00	180.00
			15,778.00
		Less 10%	1,577.80
			14,200.20
9 Rear windscreen sealant	1	60.00	60.00

SPECIAL NET

9 Rear windscreen sealant



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : GBG1070E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2018

ACCIDENT DATE : 19/09/2021

TP VEH REG NO : GBG1070E

ESTIMATE

NO : QUOT202110-000004(00)
DATE : 01/10/2021
POLICY NO : 999995580
VEH REG NO : SML6308G
MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)
CHASSIS NO : WDD2050402R470129
ENGINE NO : 27491031665902

Estimate Repair Cost to Vehicle No : SML6308G

Description	Quantity	Unit Price	Amount
		S\$	S\$
LABOUR			60.00
30 To remove and refit rear windscreen glass	1	150.00	150.00
31 To remove and refit rear interior garnish and trimboard to facilitates the repairs	1	180.00	180.00
32 To transfer LH rear damaged door interior mechanism and glass to new door	1	150.00	150.00
33 To remove and refit rear bumper sensor	1	100.00	100.00
34 To check and rectify wiring system	1	80.00	80.00
35 To panel beat and straighten LH rear fender inner panel, LH rear chassis frame, to cut and weld rear end panel, LH rear taillamp panel, LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00
36 To putty and spray paint on affected areas	1	1,800.00	1,800.00
37 To supply rust-proofing on replaced and repaired panels	1	160.00	160.00
			4,420.00
		18,964.60	TOTAL S\$ 18,680.20
			ADD GST @ 7% 1,307.61
			GRAND TOTAL S\$ 19,987.81

SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED EIGHTY-SEVEN AND CENTS EIGHTY-ONE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : GBG1070E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 19/09/2021

TP VEH REG NO : GBG1070E

ESTIMATE

NO : QUOT202110-000004(00)

DATE : 01/10/2021

POLICY NO : 999995580

VEH REG NO : SML6308G

MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)

CHASSIS NO : WDD2050402R470129

ENGINE NO : 27491031665902

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SML6308G

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY NET PRICE			
1 Taillamp lower bracket - LH	1	95.00	95.00
2 Rear fender control module mount bracket - LH	1	169.00	169.00
3 Rear fender air grille - LH	1	52.00	52.00
			316.00
		Less 10%	31.60
			284.40
		TOTAL	S\$ 284.40
		ADD GST @ 7%	19.91
		GRAND TOTAL	S\$ 304.31

SINGAPORE DOLLAR THREE HUNDRED FOUR AND CENTS THIRTY-ONE ONLY

parts : \$ 10,411.20

SN 90.00

Labour : 2,510.00

Supp : 284.40

\$ 13,295.60

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE