



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : SML6308G

Yours Ref : SNM21D205331/C04

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

17 November 2021

3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE 079909
SINGAPORE
Attn: MOTOR CLAIM DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SML6308G & GBG1070E ON 19/09/2021 @ 10:00 HRS ALONG
JUNCTION OF UPPER JURONG ROAD AND PIONEER ROAD

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair	:	S\$14,222.44
Loss of Use (\$150.00 x 9days)	:	S\$1,350.00
Additional Loss of Use (\$150.00 x 1day) - Weekend	:	S\$150.00
GIA / LTA Search	:	S\$7.45
		<u>S\$15,729.89</u>

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of SML6308G hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: SML6308G that was damaged pursuant to the accident which occurred on 19/09/2021 ALONG JUNCTION OF UPPER JURONG ROAD AND PIONEER ROAD involving vehicle nos: GBG1070E, GBC3114X, SMY4426T

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a

Dated this 17th day of November 2021




hashim

Signed by third party claimant



TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : SNM21D205331/C04

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 19/09/2021

TP VEHICLE NO : GBG1070E

NO : AR202111-0036
CLAIM NO : QUOT202110-000004(01)
DATE : 17/11/2021
POLICY NO : 999995580
VEH REG : SML6308G
MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)
CHASIS NO : WDD2050402R470129
ENGINE NO : 27491031665902
REG. DATE : 2018

Final Repair Cost to Vehicle No : SML6308G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Bootlid	1	2,405.00	2,405.00
2 Bootlid centre chrome	1	147.00	147.00
3 Bootlid weatherstrip	1	220.00	220.00
4 Bootlid centre logo	1	54.00	54.00
5 Bootlid 'C180' emblem	1	109.00	109.00
6 Bootlid '9G-TRONIC' emblem	1	128.00	128.00
7 Rear end panel	1	1,578.00	1,578.00
8 Taillamp panel - LH	1	180.00	180.00
9 Taillamp assy - LH	1	775.00	775.00
10 Taillamp lower bracket - LH	1	95.00	95.00
11 Rear fender - LH	1	2,556.00	2,556.00
12 Rear fender granish - LH	1	208.00	208.00
13 Rear fender inner trim - LH	1	325.00	325.00
14 Rear fender inner trim cover - LH	1	88.00	88.00
15 Rear fender control module mount bracket - LH	1	169.00	169.00
16 Rear bumper	1	1,805.00	1,805.00
17 Rear bumper side retainer - LH	1	65.00	65.00
18 Rear fender air grille - LH	1	52.00	52.00
19 Rear bumper lower spoiler	1	292.00	292.00
20 Rear bumper lower chrome	1	321.00	321.00
21 Rear bumper sensor	1	195.00	195.00
22 Rear bumper sensor seals	4	12.00	48.00
23 Rear bumper bracket - LH	1	65.00	65.00
			11,880.00
		Less 10%	1,188.00
			10,692.00
SPECIAL NET			
24 Rear windscreen sealant	1	40.00	40.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : SNM21D205331/C04

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 19/09/2021

TP VEHICLE NO : GBG1070E

NO : AR202111-0036
CLAIM NO : QUOT202110-000004(01)
DATE : 17/11/2021
POLICY NO : 999995580
VEH REG : SML6308G
MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)
CHASIS NO : WDD2050402R470129
ENGINE NO : 27491031665902
REG. DATE : 2018

Final Repair Cost to Vehicle No : SML6308G

Description	Quantity	List Price	Amount
		S\$	S\$
25 Rear bumper clips (set)	1	50.00	50.00
			90.00
LABOUR			
26 To remove and refit rear windscreen glass	1	120.00	120.00
27 To remove and refit rear interior garnish and trimboard to facilitates the repairs	1	120.00	120.00
28 To remove and refit rear bumper sensor	1	60.00	60.00
29 To check and rectify wiring system	1	20.00	20.00
30 To panel beat and straighten LH rear fender inner panel, LH rear chassis frame, to cut and weld rear end panel, LH rear taillamp panel, LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
31 To putty and spray paint on affected areas	1	900.00	900.00
32 To apply rust-proofing on replaced and repaired panels	1	90.00	90.00
			2,510.00

TOTAL: **S\$13,292.00**

ADD GST @ 7%: 930.44

GRAND TOTAL: **S\$14,222.44**

SINGAPORE DOLLARS FOURTEEN THOUSAND TWO HUNDRED AND TWENTY-TWO AND CENTS FORTY-FOUR ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 23 Sep 2021 / 15:51:32

Receipt Date/Time : 23 Sep 2021 / 15:51:32

Tax Invoice/Receipt

Receipt No. : ITNET-00000-210923-002658

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBG1070E				
As at 19 Sep 2021/10:00:00				
Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD				
1	Insurance Enquiry - GBG1070E			
	Enquiry Fee	7.00	0.49	7.49
	20210923154932512473			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	518834XXXXXX2002	eNETS Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No.	Incident Date/Time	Insurance Company Name
GBG1070E	19 Sep 2021 / 10:00:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Save as PDF](#)

[OK →](#)

[Print](#)