

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 04.10.2021

RE: VEHICLE REPAIR QUOTATION

Insurance Company

Vehicle Reg No

Name of Insured

Policy Number

Date of Accident

Tyre of Claim

Model

Chassis No

LONPAC INSURANCE BHD

SCU1000Y

Own Damage Cxclaim

TOYOTA WISH

JTDGG20W50J004937

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	REAR BOOT	B \$ 1,477.00	✓
2	REAR BOOT CHROME	CM \$ 370.00	✓
3	REAR BOOT LOGO (TOYOTA)	AL \$ 66.00	✓
4	REAR WINDSCREEN	SL \$ 1,300.00	X
5	REAR WINDSCREEN MOULDING	AL \$ 129.00	✓
6	REAR BOOT LOCK	\$ 361.00	?
7	REAR BOOT ABSORBER	SL \$ 217.00	X
8	REAR BOOT INNER TRIM CLIPS	AL \$ 8.00	X
9	REAR WEATHERSTRIP	SL \$ 330.00	X
10	REAR BUMPER	BL \$ 491.00	✓
11	SIDE RETAINER RH	SL \$ 89.00	X
12	SIDE RETAINER LH	D/S \$ 89.00	✓
13	REFLECTOR RH	SL \$ 55.00	X
14	REFLECTOR LH	SL \$ 55.00	X
15	REAR BOOT LAMP LH	CM \$ 360.00	✓
16	REAR BOOT LAMP RH	SL \$ 360.00	X
17	REAR BUMPER CLIPS	AL \$ 5.00	✓
18	REAR END PANEL	\$ 453.00	?
19	REAR END PANEL TOP GARNISH	\$ 253.00	?
20	TOP GARNISH CLIPS	\$ 6.00	?

Sub Total Parts \$ 6,474.00

Less 25% ADB 40% \$ 647.40

Total Parts \$ 7,121.40

1	Sundries	\$ 150.00	?
2	Wiring connection and check.	\$ 150.00	201
3	Tuff kote and spray anti rust proofing	\$ 150.00	?
4	Labour charges to dismantle & refix rear bumper rear boot, rear end panel, spare tyre panel To repair and adjust affected portion to specific dimension.	\$ 1,000.00	600
5	To remove and refix rear windscreen conduct water leak test	\$ 150.00	1201

6	To supply windscreen sealant for rear windscreen	\$	60.00	405N
7	Inner seal for rear windscreen	\$	50.00	305N
8	transfer rear boot mechanism, locks, trims scuff plates. Motor and all all other affected parts	\$	200.00	601
9	Sealant for rear boot, rear end panel	\$	150.00	?
10	To supply and install rear number plate with holder	\$	55.00	455N
11	To supply and install rear bumper reverse sensor	\$	380.00	501
12	To remove and refix rear reverse camera conduct distance setting	\$	150.00	501
13	To spray paint rear bumper, rear boot rear end panel, spare tyre panel and all other accident affected portion	\$	1,000.00	6601
14	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	350.00	?
		\$	3,545.00	
		\$	<u>3,995.00</u>	
	Total (Labour)			
		\$	11,116.40	
	Sub Total :	\$	778.15	
	GST 7%	\$	<u>11,894.55</u>	
	Grand Total :			

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: