

TTS EUROCARS PTE LTD
383 Sin Ming drive Singapore 575717

Date : 04.10.2021

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	LONPAC INSURANCE BHD
Vehicle Reg No	:	SCU1000Y
Name of Insured	:	
Policy Number	:	
Date of Accident	:	
Tyre of Claim	:	Own Damage Cxclaim
Model	:	TOYOTA WISH
Chassis No	:	JTDGG20W50J004937

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	REAR BOOT	B \$ 1,477.00	✓
2	REAR BOOT CHROME	CM \$ 370.00	✓
3	REAR BOOT LOGO (TOYOTA)	nn \$ 66.00	✓
4	REAR WINDSCREEN	sn \$ 1,300.00	X
5	REAR WINDSCREEN MOULDING	nn \$ 129.00	✓
6	REAR BOOT LOCK	R \$ 361.00	X
7	REAR BOOT ABSORBER	sn \$ 217.00	X
8	REAR BOOT INNER TRIM CLIPS	nn \$ 8.00	X
9	REAR WEATHERSTRIP	sn \$ 330.00	X
10	REAR BUMPER	Bn \$ 491.00	✓
11	SIDE RETAINER RH	sn \$ 89.00	X
12	SIDE RETAINER LH	D/S \$ 89.00	✓
13	REFLECTOR RH	sn \$ 55.00	X
14	REFLECTOR LH	sn \$ 55.00	X
15	REAR BOOT LAMP LH	CM \$ 360.00	✓
16	REAR BOOT LAMP RH	sn \$ 360.00	X
17	REAR BUMPER CLIPS	nn \$ 5.00	✓
18	REAR END PANEL	R \$ 453.00	X
19	REAR END PANEL TOP GARNISH	sn \$ 253.00	X
20	TOP GARNISH CLIPS	nn \$ 6.00	X

Sub Total Parts \$ 6,474.00
 Less 25% \$ 1,618.50
 ADD 10% \$ 647.40
Total Parts \$ 7,121.40

1	Sundries	\$ nn 150.00	X
2	Wiring connection and check.	\$ 150.00	201
3	Tuff kote and spray anti rust proofing	\$ 150.00	301
4	Labour charges to dismantle & refix rear bumper rear boot, rear end panel, spare tyre panel To repair and adjust affected portion to specific dimension.	\$ 1,000.00	6801
5	To remove and refix rear windscreen conduct water leak test	\$ 150.00	1201

6	To supply windscreen sealant for rear windscreen	\$	60.00	40sn
7	Inner seal for rear windscreen	\$	nn 50.00	30sn
8	transfer rear boot mechanism, locks, trims scuff plates. Motor and all other affected parts	\$	200.00	60l
9	Sealant for rear boot, rear end panel	\$	nn 150.00	X
10	To supply and install rear number plate with holder	\$	0.1 55.00	45sn
11	To supply and install rear bumper reverse sensor	\$	380.00	50l
12	To remove and refix rear reverse camera conduct distance setting	\$	150.00	50l
13	To spray paint rear bumper, rear boot rear end panel, spare tyre panel and all other accident affected portion	\$	1,000.00	660l
14	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	nn 350.00	X
		\$	3,545.00	
	Total (Labour)	\$	3,995.00	
	Sub Total :	\$	11,116.40	
	GST 7%	\$	778.15	
	Grand Total :	\$	11,894.55	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey -s on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: