

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC5196A

Not Authorized
Repair By paint
 AAD2110-

Vehicle No.: 05 OCT 2021 PARTS SHC5196A
 Chassis No.: JTDKB3FU303092735
 Vehicle Make: TOYOTA
 Vehicle Model: PRIUS GEN 4
 Date of Accident : 03/10/2021
 Third Party Insurer : III/MSIG
 Date of Registration: 20/11/2020

PART	LIST	
1 COVER, REAR BUMPER	\$ 485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ 332.70	?
1 COVER, REAR BUMPER, LOWER	\$ 22.00	X
1 GUARD, REAR BUMPER, CENTER	\$ 374.50	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ 132.60	✓
1 RETAINER, REAR BUMPER SIDE, RH	\$ 132.60	X
1 REFLECTOR ASSY, REFLEX, LH	\$ 39.00	X
1 DUCT ASSY, QUARTER VENT, LH	\$ 67.00	X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$ 339.60	?
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$ 261.00	✓
1 PANEL SUB-ASSY, QUARTER, LH	\$ 871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$ 139.80	X
1 COVER, FLOOR UNDER, NO.1 (LH)	\$ 175.10	X
1 COVER, REAR FLOOR (CTR)	\$ 229.90	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ 651.00	X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ 913.60	X
TOTAL	\$ 5,167.50	
25%	\$ 1,291.88	
	\$ 3,875.63	

Special Nett	
1SET PARKING AID	\$ 700.00 X
1SET REAR BUMPER CLIP	\$ 95.00 5050
1 RIM	\$ 1,879.40 X
1 TYRE	\$ 350.00 X
1 REAR FENDER CLIP	\$ 60.00 X
1 REAR FENDER LINER CLIP	\$ 60.00 X
TOTAL	\$ 795.00

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC5196A

AAD2110-

TOTAL PARTS \$ 4,670.63

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	4401

Trans-cab Auto Services Pte Ltd

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5196A

To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 220.00	X
To replace, refix and top up coolant for radiator	\$	na 170.00	X
To lift-up / out engine with gear box and refit.	\$	na 440.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	na 380.00	X

TOTAL \$ 9,610.00

Over All Total \$ 14,280.63

(PART-BY-PART) Repair Days ~~25 DAYS~~
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: