

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

forward to Wtds
XD1416Y
TP/India

M/S: INDIA INTL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100
ATTN: Motor Claim Department
WS Ref: TP/INDIA
Claim Type: Third Party
Accident Date: 01/10/2021
TP Veh Reg No: YN3402J

FAX: 62247743

Not available
11 Pm @
Presumy After Rain
7 days

Estimate No: ES2190949/YISHUN
Date: 05 Oct 2021
Policy No: 5122190411
Veh Reg No: XD1416Y
Make/Model: ISUZU ISUZU FVR34P
Chassis No: JALFVR34P77000014
Engine No: 6HK1450903
Reg. Date: 11/06/2007

Estimate Repair Cost to Vehicle No :XD1416Y

Description	U/Price	Quantity	List Price	Amount
List Price			S\$	S\$
1 FRONT LH DOOR	1,338.00	1 PC	1,338.00	✓
2 FRONT LH DOOR LOWER PROTECTOR	244.00	1 PC	244.00	✓
3 FRONT LH DOOR LOWER PROTECTOR COVER	25.00	1 PC	25.00	✓
4 FRONT LH DOOR PROTECTOR CLIPS	39.00	1 SET	39.00	✓
5 FRONT LH DOOR KEY LOCK	64.00	1 PC	64.00	✓
6 FRONT LH DOOR INNER RUBBER	91.00	1 PC	91.00	✓
7 FRONT LH DOOR INNER LOCK	268.00	1 PC	268.00	X
8 FRONT LH MUDGUARD	481.00	1 PC	481.00	✓
9 FRONT LH MUDGUARD LAMP	128.00	1 PC	128.00	✓
10 FRONT LH WHEEL ARP GARNISH	292.00	1 PC	292.00	✓
11 FRONT LH WHEEL ARP GARNISH CLIPS	45.00	1 SET	45.00	✓
12 CABIN REAR LH SIDE PANEL	754.00	1 PC	754.00	✓
13 REAR LH WHEEL MUDGUARD	170.00	1 PC	170.00	✓
14 FRONT LH TYRE RIM	1,520.00	1 PC	1,520.00	✓
15 DIESEL TANK	1,702.00	1 PC	1,702.00	X
			7,161.00	
	Less 15%		1,074.15	6,086.85
Special Net				
16 LH SAFETY BAR	620.00	1 PC	620.00	✓
17 FRONT LH TYRE	480.00	1 PC	480.00	808.00 384
			1,100.00	1,100.00
Labour				
18 REMOVE & REFIX FRT LH DOOR,TRANSFER LOCK ASSY,GARNISH,REMOVE & REFIX PROTECTOR,MUDGUARD ASSY,WHEEL ARP GARNISH,CUT,WELD & RENEW CABIN REAR LH SIDE PANEL,KNOCK & REPAIR INNER PANEL,FRT LH WHEEL ARP PANEL & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1100
19 REMOVE & REFIX CABIN REAR LH SIDE PANEL GLASS	100.00	1 LA	100.00	60
20 REMOVE & REFIX FRT LH DOOR GLASS	80.00	1 LA	80.00	✓

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INTL INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 01/10/2021

TP Veh Reg No: YN3402J

Estimate No: ES2190949/YISHUN

Date: 05 Oct 2021

Policy No: 5122190411

Veh Reg No: XD1416Y

Make/Model: ISUZU ISUZU FVR34P

Chassis No: JALFVR34P77000014

Engine No: 6HK1450903

Reg. Date: 11/06/2007

Estimate Repair Cost to Vehicle No :XD1416Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
21 REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING,GARNISH	150.00	1 LA	150.00	120/-
22 PUTTY & RESPRAY ON FRT LH DOOR, PROTECTOR, WHEEL ARP GARNISH, CABIN REAR LH SIDE PANEL INNER & OUTER, LH SIDE PANEL, SAFETY BAR	1,000.00	1 LA	1,000.00	900/-
23 REMOVE & REFIX DIESEL TANK AND REPAIR DIESEL TANK BRACKET	150.00	1 LA	150.00	80/-
24 TO REWRITE ADVERTISEMENT	380.00	1 LA	380.00	240/-
			3,160.00	3,160.00

Total SS 10,346.85

Add GST @ 7% 724.28

Total Amount Payable SS 11,071.13

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Parts \$ 5100
15% 765
4335
45.505N
384 SN
620 SN
2580
7964.50
45 \$ 6350