

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21010210/EGA3Q2

Date:

05/01/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MCV0003239_01

Claimant Vehicle No : SNB7740A**Insured Vehicle No :**

GBD8719M

Date of Loss: 01/10/2021

Nature of Claim:

TP

Claim No:

MCV2021D0004477

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB7740A**

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A)

Engine No: CZDC20567

Reg. Date: 14/09/2021 (Man. Year: 2021)

Chassis No: WVGZZZ1TZW027147

Colour: White

Odometer: 610 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,144.41	2,144.41	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	2,820.00	3,700.00	56.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,664.41	4,964.41	3,700.00	42.70
+ GST 7.00/7.00% (S\$)	606.51	347.51	259.00	42.70

Nett Amount (S\$)	9,270.92	5,311.92	3,959.00	42.70
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,640.37		

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 05/10/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2021)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB7740A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR LHS REAR DOOR	Dented	1,754.22 FS	*1,754.22 FS
2	1		*DOOR SEAL OUTER BLACK	Necessary	158.07 FS	*158.07 FS
3	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	31.43 FS	*31.43 FS
4	2		*BOLT WITH POLYGON SOCKET	Necessary	7.44 FS	*7.44 FS
5	1		*WINDOW SLOT SEAL WITH BLA LHR DOOR GLASS OUTER MLDG CHROM	Bent	109.73 FS	*109.73 FS
6	1		*TRIM FOR DOOR WINDOW FRAM LHR DOOR TRIM (BLACK)	Necessary	79.55 FS	*79.55 FS
7	1		*FILL.HD.SCREW (2 PCS)	Necessary	3.97 FS	*3.97 FS
					Total Parts (\$\$)	2,144.41
						2,144.41

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	2,400.00	800.00
5	TRANSFER DOOR MECHANISM	New	840.00	420.00
Gross Labour Cost (S\$)			6,520.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >