

ASS. REQ. BY:

Steve

CS/CT121010217/EVC

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Gilon's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its
repair at the time of inspection.



Real. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

F3M 1889C

Yr Regn:

7/8/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SYM COMBIZ

C.C.

125

Colour:

White

AJO:

Insured / Std / NI / IN

Sp. Reading

34172

TIRadio:

Insured / Std / NI / IN

Eng/No:

C/No:

REGAPA 301.HIS093321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

J-50-10

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

U/Bal.

mm

D.O.A.

29/6/21

D.O.A.

5/10/21

Survey held at

Unique Motors

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-SK

Date/Time, File, Pass to:



: Prelim. Report



: Final Report

Date/Time, File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Wash and (\$

S + RS \$

Fees

Others

TOTAL

Signature:

Signature / Date:



UNIQUE MOTORSPORTS PTE LTD

48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIRD PARTY

Vehicle No. : FBM1880C

Make & Model : SYM COMBIZ 125A

Year of Manufacture : 2017

Chassis No. : RFGAPA301HS003321

Engine No. : KZ703327

Policy No. : _____

Time of Accident : 16:30

Ins Company : Great Eastern General Insurance Ltd

Excess : _____

Date of Accident : 29/06/2021

Suggested Days of Repair : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Contact No

8188 8999 – ALVIN KOH

Repair Estimates

Parts (a) Cost / List Price Items \$1,298.00

Plus/Less \$-

Total of Cost / List \$1,298.00

(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$-

Total Parts Cost (Appendix A) \$1,298.00

Labour (Appendix B) \$250.00

Total Repair Cost \$1,548.00

The above total will be subjected to 7% G.S.T.

Steve (LKK)
83228813
5/10/21, 11.00am

ML PL
3 dys
L/S
My ML SL

Name of Surveyor :

Company :

Survey conducted on :

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

at Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Unique Motorsports Pte Ltd
48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586

Spare Parts

Vehicle No : FBM1880C Case Owner : 0

Make & Model : SYM COMBIZ 125A Year Manufacture : 2017

Chassis No : RFGAPA301HS003321 Engine No : KZ703327

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : THIRD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FIBER BOX (respray) / CUT	1		\$200.00	150		
2	STICKER SINGPOST - FIBER BOX	1		\$160.00			
3	MIRROR SET / CUT	1		\$65.00			
4	BRAKE LEVER / BR	1		\$45.00			
5	EXHAUST PROTECTOR / BR	1		\$75.00			
6	SIDE STAND ASSY / BT	1		\$118.00			
7	FRONT UNDER SPOILER / CUT	1		\$170.00			
8	FRONT COVER SUB ASSY / CUT	1		\$240.00			
9	FRONT FENDER / CUT	1		\$105.00			
10	RESPRAY & PUTTY WORKS	1		\$120.00	190		
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour

[illegible]

Scanned with CamScanner