



UNIQUE MOTORSPORTS PTE LTD

48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIRD PARTY

Vehicle No. : FBM1880C

Make & Model : SYM COMBIZ 125A

Year of Manufacture : 2017

Chassis No. : RFGAPA301HS003321

Engine No. : KZ703327

Policy No. : _____

Time of Accident : 16:30

Ins Company : Great Eastern General Insurance Ltd

Excess : _____

Date of Accident : 29/06/2021

Suggested Days of Repair : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Contact No

8188 8999 - ALVIN KOH

Repair Estimates

Parts (a) Cost / List Price Items \$1,298.00

Plus/Less : \$-

Total of Cost / List \$1,298.00

(b) Nett Price Items \$-

Less : _____

Total of Nett Item _____

(c) Special Nett Items \$-

Total Parts Cost (Appendix A) \$1,298.00

Labour (Appendix B) \$250.00

Total Repair Cost \$1,548.00

The above total will be subjected to 7% G.S.T.

Steve (LKK)
83228813
5/10/21, 11.00am

ML PL
3 4/5
L/S
My ML SL

Name of Surveyor : _____

Company : _____

Survey conducted on : _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- at Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Spare Parts

Vehicle No

FBM1880C

Case Owner

0

Make & Model

SYM COMBIZ 125A

Year Manufacture

2017

Chassis No

RFGAPA301HS003321

Engine No

KZ703327

Sales Order

Supplier

Order By

Type of Claim

THIRD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FIBER BOX (respray) / CUT	1		\$200.00	150 nett		
2	STICKER SINGPOST - FIBER BOX - APC	1		\$160.00	120 /		
3	MIRROR SET / CUT	1		\$65.00	45 /		
4	BRAKE LEVER / BR	1		\$45.00	30 /		
5	EXHAUST PROTECTOR / BR	1		\$75.00	60 /		
6	SIDE STAND ASSY / BT	1		\$118.00	100 /		
7	FRONT UNDER SPOILER / CUT	1		\$170.00	140 /		
8	FRONT COVER SUB ASSY / CUT	1		\$240.00	180 /		
9	FRONT FENDER / CUT	1		\$105.00	90 /		
10	RESpray & PUTTY WORKS	1		\$120.00	190 nett		
11	0	0					
12	0	0					
13	0	0					
14	0	0		P- 765			
15	0	0		-10%			
16	0	0		688.50			
17	0	0					
18	0	0		N- 250			
19	0	0					
20	0	0					
21	0	0		L- 200			
22	0	0		1138.50			
23	0	0					
24	0	0		LIS-910.80			
25	0	0		= 900			
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

UNIQUE MOTORSPORTS PTE LTD
48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586

Labour

Vehicle No. : FBM1880C

Case Owner : 0

Make & Model : SYM COMBIZ 125A

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any further work will be quote accordingly as a supplementary.