

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|---|-----------------|--------------------|--|
| | CHINA TAIPING IN | ISURANCE (S) PTE LTD | Ref: | CS/CTI21010217/Evc | |
| | 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | Date: | 04/10/2021 | |
| | | | Code | : CTI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SML 9849S | Veh. Inspected | FBM 1880C | |
| | Policy No. | DMHCSNW00005192100 | Coverage (\$) | 0.00 | |
| | Claim No. | SNM21D203979/C02/TANKL | Excess (\$) | 0.00 | |
| | Assign From | TAN KAH LEONG | Assign Date | 04/10/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | - | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | | | mm | |
| | L/H Front Tyre | | | mm | |
| | R/H Rear Tyre | | | mm | |
| | L/H Rear Tyre | | | mm | |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 29/06/2021 | Inspection Date | 05/10/2021 | |
| | Survey held at | 48 Toh Guan Road East, #02-140 Enterprise Hub | | | |
| | Repairer | UNIQUE MOTOR SPORTS | | | |
| 5a. | ia. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |