

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH977R

MAKE & MODEL : NISSAN NV200

CHASSIS NO : VSKYBAM20Z0152781

DATE : 12/10/2021

CLAIM TYPE : TP CLAIM

D.O.A : 23 SEPTEMBER 2021

TO : LONPAC INSURANCE BHD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	FRONT FENDER LH	DO	\$ 555.20	\$ 555.20
2	1	FRONT FENDER SIGNAL LAMP LH	X	\$ 61.60	\$ 61.60
3	1	FRONT DOOR LH	DO	\$ 1,287.50	\$ 1,287.50
4	2	FRONT DOOR HINGE LH	X	\$ 58.90	\$ 117.80
5	1	ROCKER PANEL LH	DO	\$ 1,353.60	\$ 1,353.60
6	1	SLIDING DOOR LH	X R	\$ 1,229.90	\$ 1,229.90
7	0	0		\$ -	\$ -
				\$ 4,546.70	\$ 4,605.60

TOTAL PRICE \$ 4,605.60

LESS 10% \$ 460.56

SUB TOTAL PRICE \$ 4,145.04

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	DOOR CO. REG STICKER	MC	\$ 30.00	\$ 30.00

TOTAL S/NETT \$ 30.00 \$ 30.00

Labour Charges

1	To cut & weld LH rocker panel, panel beat & replace LH front fender and damaged parts	\$ 1,200.00	1000
2	To transfer LH front door parts and mechanisms to new door	\$ 150.00	50
3	To transfer LH sliding door parts and mechanisms to new door	\$ 150.00	X
4	To check and rectify lighting & wiring.	\$ 80.00	30
5	To spray paint LH front fender, LH front door, LH sliding door, LH rocker panel	\$ 1,400.00	500
6	To conduct wheel alignment	\$ 120.00	X

TOTAL LABOUR

\$ 3,100.00

Total Cost of Repairs

\$ 7,275.04

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK)

6/12/21, 10:00am

ML PL

6 dys

L/S

My 11/11/21

LKK Auto Consultants hereby notify the Repeller of the following:

- To rectify/replace/spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repeller:

Signature:

Date: