

TP China
Justin

107261Ar

GBE9769G. 2016 May.

Nissan NV350 2488CC

JN1MC2E26Z0006175

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Front Bumper torn 571.90 ✓

30(SN) ✓

Front Bumper clips. New

Cracked 104.50 ✓

Front Bumper Side Holder RH.

Front Bumper Fog Lamp RH 323.70 +

Not
Nec

Front Bumper Fog Lamp Cover RH. 130.10 +

Headlamp RH. 403 ✓

Nett: 1079.40

Len 10%: 971.46

Front RH Door

Regis

1237.90. +

S.N: 30

Front RH Door Company Address Sticker. 30(SN) ✓

Labour: 730

Total: 1731.46

L/S: 1350

03 Days

Panel Beating

Spray Painting.

Wiring.

To transfer door fittings.

~~600~~ 300

~~600~~ 400

~~50~~ 30

150 +