

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : D21MFL0000447 Date: 11th Oct 2021

Our Ref : CS/III21010239/Kuf3e2

M/s India International Insurance PL

64 Cecil Street #05-02 IOB Building Singapore 049711 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLR 8461M ACCIDENT ON 01/10/2021

Instruction was received to inspect the vehicle Reg. No. SLR 8461M. The inspection was conducted on 05/10/2021 at the premises of M/s 385 Sin Ming Drive, Repairer: Esteem Performance Pte Ltd.

The following vehicle information was recorded:

Registration Number : SLR 8461M

Make/Model : Honda Vezel Hybrid 1.5X Auto

Year of Registration : 2017

Body Colour : Metallic Grey Chassis Number : RU31255747

Engine Capacity : 1496 cc

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$40,000.00 (Sin Dollars: Forty Thousand only.) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

(a)	If the vehicle to be "Total Loss"

Market Value

S\$ 62,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 31,752.00)

S\$

Nett Liability

30,248.00

S\$

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 40,000.00

Nett Liability

S\$ 40,000.00

(a) - (b) =

(S\$ 9,752.00)

30,248.00

The amount of estimated saving of S\$9,752.00 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.