

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS/III21010239/Kuf3 Date: 05/10/2021 Code: III2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SLR 8461M	
Policy No.	D21MFL0000447		Coverage (\$)	
Claim No.			Excess (\$)	
Assign From	BHUVANESWARI		Assign Date	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/10/2021		Inspection Date	05/10/2021
Survey held at	385 Sin Ming Drive			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				