

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Zuhaidah Bte Samsuri

Date: 06 Oct 2021

**Preliminary Advice**

Vehicle No	: SLR8461M	Accident Date	: 01/10/2021
Make	: HONDA VEZEL	Policy No.	: D21MFL0000447
Assignment Date	: 05/10/2021	Excess	: S\$0.00
Date of Inspection	: 05/10/2021	Est. Duration of Repair	: 0
Inspection At	: ESTEEM PERFORMANCE PTE LTD (HQ) 176 SIN MING AUTOCARE SIN MING DRIVE, #01-14 & #01-15 & #01-16 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	31,752.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,248.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :