

進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E


MR INDIA INTERNATIONAL INSURANCE PTE LTD	POLICY NO	: D19MCV0000229_02
64 CECIL STREE	OUR REF	: OD 3474
#04/05/06-02	VEHICLE NO	: YN 3402 J
IOB BUILDING	MAKE/MODEL	: MIT FE83
SINGAPORE 049711	CHASSIS	: FE83BEA20939
ATTN: MOTOR CLAIMS DEPT	DATE OF ACCIDENT	: 01.10.21

SURVEY BY

DATE : 04.10.21

1 PC	FRONT WINDSCREEN GLASS <i>cm</i>		S\$	1,338.08
1 PC	FRONT WINDSCREEN GLASS RUBBER <i>an</i>			387.00
1 PC	FRONT WINDSCREEN PILLAR RH <i>bt</i>			1,240.95
1 PC	WIPER ARM, WIPER BLADE, WIPER COVER <i>sc</i>			129.82
1 PC	WIPER GRILLE <i>sc</i>			383.26
1 PC	WIPER GRILLE "CANTER" STICKER <i>an</i>			84.37
1 PC	FRONT CORNER PANEL RH <i>bn</i>			398.41
1 PC	FRONT CORNER PANEL LOWER RUBBER RH <i>an</i>			25.92
1 PC	SIDE MIRROR RH <i>bn</i>			107.67
1 PC	SIDE MIRROR BRACKET RH <i>cm</i>			252.90
1 PC	SIDE MIRROR COVER RH <i>ms</i>			64.03
1 PC	FRONT PANEL <i>bt</i>			1,115.92
1 PC	FRONT GRILLE <i>sc</i>			383.26
1 PC	FRONT GRILLE EMBLEM <i>an</i>			57.12
1 PC	FRONT GRILLE "FUSO" EMBLEM <i>an</i>			107.24
8 PCS	FRONT GRILLE CLIPS <i>an</i>	8.00		80.00
1 PC	HEADLAMP ASSY RH <i>bn</i>			721.25
1 PC	HEADLAMP LOWER RUBBER RH <i>ms</i>			15.00
1 PC	SIGNAL LAMP RH <i>bn</i>			206.01
1 PC	SIDE LAMP RH <i>bn</i>			139.05
1 PC	FRONT BUMPER <i>bt</i>			999.86
1 PC	FRONT BUMPER BRACKET <i>bt</i>			151.71
1 PC	FRONT DOOR RH <i>bt</i>			1,910.15
1 PC	FRONT DOOR OUTER GARNISH RH <i>sc</i>			51.35
1 PC	FRONT DOOR TOP MOULDING RH <i>sc</i>			100.15
1 PC	FRONT DOOR OUTER MOULDING RH <i>?</i>	NN		120.00
2 PCS	FRONT DOOR HINGES <i>bt</i>	131.60		263.20
1 PC	FRONT DOOR WEATHERSTRIP RH <i>an</i>			408.22
1 PC	FRONT DOOR INNER TRIM BOARD RH <i>?</i>	NN		541.25
1 PC	FRONT DOOR INNER LOCK RH <i>X</i>	SVC		535.76
1 PC	FRONT DOOR REGULATOR GEAR WITH MOTOR <i>X</i>	SVC		1,028.59
1 PC	FRONT DOOR JACK RH <i>bt</i>			78.60
1 PC	FRONT DOOR STEP GARNISH RH <i>sc</i>			415.44
1 PC	FRONT DOOR FRAME RUBBER RH <i>an</i>			222.83
1 PC	FRONT FENDER WHEEL ARCH GARNISH RH <i>?</i>	NN		68.04
				S\$ 14,132.41
LESS 25%				3,533.10
				S\$ 10,599.31

----- P/G 2



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/200

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1

		S\$	10,599.31	
1 PC	DASHBOARD <i>de</i>	S\$	740.19	
1 PC	DASHBOARD REINFORCEMENT <i>bt</i>		580.49	
1 PC	METER ASSY <i>?cm</i>		1,380.69	
1 PC	METER TOP GARNISH <i>?cm</i>		220.69	
1 PC	STEERING WHEEL INNER COVER <i>cut</i>		155.60	
1 PC	STEERING WHEEL OUTER COVER <i>cut</i>		177.90	
1 PC	CABIN MOUNTING <i>cm</i>		480.50	
1 PC	BRAKE BOOSTER PUMP <i>bt</i>		1,845.78	
1 PC	BRAKE OIL RESERVOIR <i>bt ?cm</i>		245.64	
		S\$	5,827.48	
	LESS 25%		1,456.87	
		S\$	4,370.61	
1 PC	ERP BRACKET <i>re</i>	S\$	26.00	S/NETT
1 PC	FRONT NO. PLATE <i>bt</i>		30.00	"
1 PC	BRAKE OIL <i>re</i>		40.00	"
		S\$	116.00	
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	<i>12 days</i>	S\$	120.00	
TO DISMANTLE AND REFIX DASHBOARD FITTING	<i>4s</i>		300.00	150
TO TRANSFER DOOR FITTING	<i>65/10/21 @ 1125</i>		100.00	60
TO REMOVE ROOF LINING, CUSHION SEAT & CARPET	<i>EXCESS: TBA</i>		120.00	60
TO TOP-UP AIR-CON GAS	<i>Revert</i>		120.00	X
TO CHECK WIRING FUNCTION	<i>Revy after repair</i>		50.00	30
LABOUR CHARGES			1,800.00	1200/1000
TO PUTTY AND SPRAY PAINTING CHARGES			1,200.00	1000
		S\$	18,895.92	

SIN DOLLARS: EIGHTEEN THOUSAND EIGHT HUNDRED NINETY-FIVE AND CENTS NINETY-TWO ONLY

YOUR FAITHFULLY,

CYS-AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: