

TO :	DATE : 5-Oct-21
ATTENTION : MOTOR CLAIMS DEPT	JOB TYPE : T/P CLAIM
OWNER'S PARTICULAR	
NAME :	VEHICLE NO : FBE6989H
ADDRESS :	MODEL : YAMAHA FZ150I
THIRD PARTY REQUESTOR / CONTACT :	

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP LH	1	\$ 350.00	\$ 160.00 350.00
2	FRONT FAIRING SIDE GARNISH LH	1	\$ 351.00	\$ 165.00 351.00
3	FRONT FAIRING SIDE BRACKET LH	2	\$ 159.00	\$ 318.00
4	FRONT FAIRING REAR GARNISH LH	1	\$ 312.00	\$ 312.00
5	FRONT FORK@ \$465.50	2	\$ 465.50	\$ 931.00
6	FRONT FORK BRACKET	2	\$ 45.00	\$ 90.00
7	RIDER SEAT LOWER STEP GARNISH LH	1	\$ 210.00	\$ 210.00
8	FOOT GEAR LEVER	1	\$ 312.00	\$ 312.00
9	CLUTCH LEVER	1	\$ 112.00	\$ 112.00
10	SEAT SIDE LOWER GARNISH LH	1	\$ 230.00	\$ 185.00 230.00
11	REAR VIEW MIRROR SET	1	\$ 95.00	\$ 95.00
12	HANDLE BAR	1	\$ 95.00	\$ 95.00
13	HANDLE BALANCER SET	1	\$ 81.00	\$ 81.00
14	HANDLE GRIP	1	\$ 76.00	\$ 65.00 76.00
15	LEG REST RH	1	\$ 98.20	\$ 98.20
16	BRAKE LEVER 1SET	1	\$ 68.50	\$ 68.50
17	LEG REST BRACKET	1	\$ 168.00	\$ 168.00
18	REAR PILLION SEAT HANDLE	1	\$ 287.00	\$ 287.00
19	EXHAUST MUFFLER PROTECTOR	1	\$ 350.00	\$ 105.00 350.00
20	REAR SIGNAL LAMP RH	1	\$ 62.00	\$ 62.00
21	REAR MUDGUARD	1	\$ 284.00	\$ 284.00
22	TAIL LIGHT	1	\$ 187.00	\$ 150.00 187.00
23	EXHAUST	1	\$ 550.00	\$ 550.00

TOTAL PRICE \$ 5,617.70

2010

CUTV

CUTV

NDX

NDX

NDX

NDX

NDX

NDX

NDX

BRV

NDX

BTX

CUTV

NECV

BTX

BRV

BRV

NDX

DDV

BRV

NDX

BRV

NDX

LESS 10%

\$ 561.77

SUB TOTAL PRICE

\$ 5,055.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SET)	1	\$ 40.00	\$ 20.00 40.00
2	HEADLAMP FAIRING STICKER	1	\$ 20.00	\$ ✓ 20.00
3	CONE BEARING	1	\$ 68.00	\$ 68.00
4	FRONT FORK OIL	1	\$ 60.00	\$ 60.00
5	REAR CARRIER BOX	1	\$ 350.00	\$ ✓ 350.00
6	REAR CARRIER BOX BRACKET	1	\$ 110.00	\$ 140.00
TOTAL			# \$	648.00

BTV
NECV
NDX
NNX
CUTV
NDX

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	ABOVE ITEMS	\$400.00	300.00
2	REMOVE, REFIT AND RE-ALIGN FORK	\$280.00	100.00
3	SPRAY AFFECTED PARTS	\$450.00	300.00
TOTAL		\$1,130.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,208.93
 TOTAL LABOUR COST : \$ 1,130.00
 TOTAL REPAIR COST : \$ 6,338.93

Parts 1262.43
 SN 390.00
 Labour 700.00
 2352.43
 @20% 470.69
 1881.94

APPROVED DETAILS

EXCESS :
 NO. OF DAYS : 4
 RE-SURVEY : 7/10/2021

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY : 5/10/2021 1400pm
 SURVEYED BY : TGLim
 CONTACT NUMBER : 97361577
 FAX NUMBER :

LS 1900/2

TGLim
 19/3/2022

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: