

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle number:

SLJ8492R

Make and model:

Toyota Harrier

Chassis:

ZSU600022224

2015

List price

Qty Spare parts

1	Bonnet	\$		1,983.80	NDX
1	Front bumper	\$	811.30	1,458.00	DDV
1	Front bumper lower garnish	\$		324.80	NDX
1	Front bumper towing cover	\$		38.90	NDX
1	Front bumper RH fog lamp cover	\$		83.90	NDX
1	Front bumper RH fog lamp assy	\$		303.80	
1	Front bumper lower grille	\$		263.70	BRV
1	Front bumper RH side retainer	\$	78.80	102.40	NEC
1	Front bumper LH side retainer	\$	78.80	102.40	
1	Front bumper reinforcement	\$		417.90	NDX
1	Front bumper sponge	\$		89.90	BRV
1	Front bumper upper beam	\$	191.60	301.10	BRV
1	Front bumper RH side beam	\$		91.50	NSX
1	Front bumper RH side beam sponge	\$		35.60	BRV
1	Front grille	\$		545.00	BRV
1	RH headlamp assy	\$	2821.10	3,303.10	BRV
1	LH headlamp assy	\$	2821.10	3,303.10	BRV
1	Front RH fender	\$		1,022.00	NDX
1	Front RH fender splash shield	\$		156.60	
1	Support panel	\$		1,545.50	NDX
1	Support panel top cover	\$		396.60	

\$ 7,736.90 15,869.60

-25% \$ 1,934.25 3,967.40

\$ 5,802.68 11,902.20

Qty Spare parts

1	Bonnet inner heat shield clips	\$		70.00	NDX
1	Front bumper clips	\$	30.00	70.00	NEC
1	Radiator-coolant				

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.

\$ 400.00 1,000.00

To panel beating, cut / weld and re-align all affected panels

Spray painting on affected panels "Pearl Colour"

\$ 200.00 1,000.00 ✓

Check wiring and lighting system

\$ 80.00 NNX

Apply rust coating chemical on affected panels

\$ 50.00 NNX

Remove and reinstall aircon condenser and pipes to assist repair

\$ 220.00 NNX

Remove and reinstall radiator assy, hoses and fan assy

\$ 220.00 NNX

600.00

Final amount: \$ 14,612.20

Survey & Resurvey

5/10/2021

1745 hrs

TG Lim Inc

Lump sum repair

Repair days 4

Parts 5,802.68

SN 30.00

Labour 600.00

6,432.68

@20% 1,286.54

5,146.14

LS 5,150/-

TG Lim Inc

6/10/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: