10/18/21, 12:49 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010257/UVY3N2

Date: 18/10/2021

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00093152100

Claimant Vehicle

FBG2259Y

Insured Vehicle No:

SGM611K

No:

Date of Loss: 07/09/2021 Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM21D205076/C02/LEEPG

RFVTRUC52C1000206

C5H10344

56764 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBG2259Y Reg No:

Make & Model: PGO TR3, 148cc 150

Reg. Date: 03/05/2012 (Man. Year: 2012)

Colour: White

Engine Capacity: 148 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 120/70-12 Rear Tyre Size: 120/70-12 Front Left Side: Rear Left Side: Timsun 6 mm Timsun 6 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,881.00	1,001.80	879.20	46.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,578.00	335.00	1,243.00	78.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,459.00	1,336.80	2,122.20	61.35
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	3,459.00	1,000.00	2,459.00	71.09
+ GST 7.00/7.00% (S\$)	242.13	70.00	172.13	71.09
Nett Amount (S\$)	3,701.13	1,070.00	2,631.13	71.09

INSPECTION

Date Inspected:

Date of Assignment: 05/10/2021

> Ban Hock Hin Co. Pte Ltd (HQ) 05/10/2021 Inspected At:

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

		_			
ட	\sim 1		-	_	\sim
$\overline{}$	_	_	_		
	u		•		ce

Part Source: (Last Synchronised: 18 Oct 2021)

Parts: N/A PGO TR3 148cc 150 (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBG2259Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP SIGNAL FRONT RH UPPER	Cracked	60.00 F	*60.00 FL
2	1		*LEFT BODY COVER (STAR ASH)(CRACKED)	Not Consistent With The Impact	231.00 F	*-FL
3	1		*MUDGUARD FRONT	Broken	182.00 F	*182.00 FL
4	1		*PLATE STEP REAR RH	Serviceable	50.00 F	*- FL
5	1		*RIGHT BODY COVER (STAR ASH)(CRACKED)	Not Consistent With The Impact	231.00 F	*-FL
6	1		*STEERING CONE ASSY	Necessary	125.00 F	*125.00 FL
7	1		*FORK FRONT ASSY	Bent/Twisted	735.00 F	*735.00 FL
8	1		*STICKER NUMBER PLATE FROTN (BLACK) STRAIGHT	Necessary	15.00 FS	*10.00 FS
9	1		*WINDSHIELD	Not Necessary	252.00 F	*- FL
F=Fra	anchise	part. S=S	SpcNett. L=ListItemDisc.			
				Sub Total (S\$)	1,881.00	1,112.00
			- List Item Disc	ount on L Items 0.00/10.00% (S\$)	0.00	110.20
				Total Parts (S\$)	1,881.00	1,001.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED-BIKE TOWED BACK TO BHH	New	80.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS }	New	1,008.00	300.00
3	REPAIR ON FRONT BODY ALIGNMENT }	New	490.00	0.00
	Gross Labour Cost (S\$)		1,578.00	335.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >