

ASS. REC. BY:

REF:

LPC / 21010265 / Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02

Res.: Yes or No

Lum Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMX 3266A

Yr Regn:

01, 21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

N. Br

A/C:

Insured / Std / Nil / NA

Sp. Reading

67571

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JTDK B3FU 903092514

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Sailun 195/63R15

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

2

mm

L/Bal.

9

mm

L/Bal.

2

mm

D.O.A.

4/10/21

D.O.I.

5/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ

8/10

1471-10 Confirm

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3266A**LAD2110-**

Not Authair
Respray B4 paint
1471.10

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

05 OCT 2021

SMX3266A

JTDKB3FU903092514

TOYOTA

PRIUS GEN 4

04/10/2021

LONPAC

07/01/2021

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, DECK TRIM, REAR

LIST

\$	<i>Acc/Res</i>	485.60	✓
\$	<i>B4</i>	332.70	✓
\$	<i>nd/ln</i>	374.50	✓
\$	<i>nu</i>	22.00	✓
\$	<i>usp</i>	132.60	X
\$	<i>usp</i>	132.60	✓
\$	<i>R</i>	651.00	X
\$	<i>ln</i>	126.70	✓

TOTAL	\$	2,257.70
25%	\$	564.43
	\$	1,693.28

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
 - 1 BUMPER CENTRE GUARD CLIP
 - 1 REAR BUMPER PROTECTOR
 - 1 REAR BUMPER RETAINER CLIP

\$	<i>ln</i>	700.00	X
\$	<i>nu</i>	85.00	<i>305nu</i>
\$	<i>nu</i>	80.00	X
\$	<i>nu</i>	180.00	<i>405nu</i>
\$	<i>nu</i>	75.00	X
TOTAL	\$	1,120.00	

TOTAL PARTS	\$	2,813.28
--------------------	-----------	-----------------

LABOUR

Trans-cab Auto Services Pte Ltd**LAD2110-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3266A

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	2201
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 300.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	nn 170.00	X

TOTAL \$ 6,240.00**Over All Total \$ 9,053.28****(PART-BY-PART) Repair Days**~~20 Days~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: