

TPAXA
Hui Zhen

SJJ145U 2008 August.

Honda Stream. 1799cc

RN61042052

Front Bumper	Distorted	683.90	/
Front Bumper Clips	Nec	30(sN)	/
Front Bumper Side Holder LH	Damaged	28.90	/
Headlamp LH	cracked	758.30	/
Headlamp Lower Bracket LH	Nec	39.50	x
Front LH Fender	Distorted	591.20	/
Front LH Fender Inner Shield	torn	142.40	/
Front LH Fender Inner Shield Clips	Nec	30(sN)	/
Front LH Fender Bracket	Best	60.10	/
Front LH Fender Signal Lamp	Cracked	38.50	/
Front LH Door	Dented	1042.80	/
Front LH Door Hinge x 02		64.20 x 2 = 128.40	+
Front LH Door Check	Nec	66.20	x

SJJ145U

Front LH Door Lock	} NH New	246.20	X
Front LH Door Weatherstripe		164.50	X
Front LH Door Wing mirror	cracked	495	✓
Front LH Door Visor	} NH New	60(SN)	✓
Front LH Door Black Tape		60(SN)	✓
Rocker Panel Outer Garnish LH	behind	655	✓
Rocker Panel Outer Garnish clips.	new	30(SN)	✓
Air Resonator Tank	x4 new	198.90	X
Front Grille	cracked	350 350(SN)	
Front Grille Logo.	} NH New	45	✓
Front Grille clips.		20(SN)	✓
Front Support Panel Top Garnish	new	211.30	X
Front Support Panel Top Garnish clips.	new	20(SN)	X
Front LH Tyre	wt	180(SN) 280(SN)	
Front LH wheel Rim.	wt	680(SN)	

450 ~~450(SN)~~

SJJ1454.

Front LH Lower Arm	Bert	328.40	✓
Front LH Shock Absorber	Bert	315.50	✓
Front LH Knuckle Arm.	HP	367	✗.
Front LH Wheel Hub c/w Bearing.	Dand	249.70	✓
Front LH Anti Roll Bar Linkage.	HP	120.50	✗
Steering Rack and Pinion.	John	1880.90	✗.

578100 S.N: 1110
4624.96

Panel Beating
Spray Painting.

Wiring.

To transfer front door fittings.

To dismantle front undercarriage.

To perform wheel alignment.

~~1200~~ ~~800~~ 900

~~1200~~ ~~900~~ 1000

2090

~~50~~ 30

~~150~~ 80

~~450~~ 200

~~150.80~~

total: 7824.96

L/S: 6250.

07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign