



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21010268/Buf3n2 Date: 19/10/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 1785E	Veh. Inspected	SMY 1845L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011953/HA	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	05/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MR2BE3BE700013650	Colour	GREY	
Odometer	39451 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	6 mm	
L/H Front Tyre	205/55 R16	NEXEN	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2021	Inspection Date	07/10/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	