

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Vehicle Nos : **SMX 4694 R**

Date of Survey :

Model : Toyota C-HR

Date of ReSurvey:

After-Paint:

Year : 2021

Contacts :

Chassis No : ZYX102163551

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,445.50	\$ 1,445.50
2	Tailgate logo	1	\$ 84.50	\$ 84.50
3	Tailgate emblem "C-HR"	1	\$ 129.60	\$ 129.60
4	Tailgate emblem "Hybrid synergy drive"	1	\$ 106.30	\$ 106.30
5	Tailgate inner lock	1	\$ 364.50	\$ 364.50
6	Tailgate inner striker	1	\$ 58.00	\$ 58.00
7	Tailgate inner trim board	1	\$ 267.80	\$ 267.80
8	Tailgate outer garnish	1	\$ 978.10	\$ 978.10
9	Tailgate lamp LH 1	2	\$ 454.00	\$ 908.00
10	Tailgate windscreen moulding	1	\$ 184.60	\$ 184.60
11	Tailgate antenna sensor	1	\$ 198.30	\$ 198.30
12	Rear bumper	1	\$ 1,124.50	\$ 1,124.50
13	Rear bumper lower lid	1	\$ 465.00	\$ 465.00
14	Rear bumper lower lid centre garnish	1	\$ 68.00	\$ 68.00
15	Rear bumper reinforcement	1	\$ 578.90	\$ 578.90
16	Rear bumper side retainer	2	\$ 68.00	\$ 136.00
17	Rear bumper tow cover	1	\$ 35.00	\$ 35.00
18	Rear bumper reflector	2	\$ 218.00	\$ 436.00
19	Rear bumper reflector garnish LH 1	2	\$ 135.00	\$ 270.00
20	Rear end panel	1	\$ 789.10	\$ 789.10
21	Rear end panel top garnish	1	\$ 285.70	\$ 285.70
22	Rear fender inner trim board LH	1	\$ 987.90	\$ 987.90
23	Rear fender arch garnish LH	1	\$ 295.00	\$ 295.00
24	Taillamp LH 1	2	\$ 585.52	\$ 1,171.04
25	Taillamp lower bracket LH 1	2	\$ 95.00	\$ 190.00
Parts Sub Total :				\$ 12,660.50
Discount :				\$ 3,165.13
PARTS TOTAL :				\$ 9,495.38

25%

DD✓
NECV
NDX
NDX
NDX
BRV
CUTV
NECV
NDX
BRV
BRV
NDX
BTU
NECV
NDX
NDX
BRV
DDXR
NDX
NSX
CUTV
BRV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 20.00 50.00
4	Tailgate outer garnish clips	1	\$ 50.00	\$ 50.00
5	Tailgate lamp clips	2	\$ 50.00	\$ 20.00 100.00
6	Tailgate lamp seal	2	\$ 60.00	\$ 120.00
7	Tailgate windscreen sealant	1	\$ 100.00	\$ 60.00 100.00
8	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00
9	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00
10	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
11	Rear bumper lower lid clips	1	\$ 50.00	\$ 20.00 50.00
12	Rear bumper reflector garnish clips	2	\$ 50.00	\$ 100.00
13	Rear end panel sealant	1	\$ 100.00	\$ 100.00
14	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
15	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
16	Rear fender arch garnish clips	1	\$ 50.00	\$ 50.00
17	Taillamp clips	LH 1	\$ 50.00	\$ 20.00 100.00
18	Taillamp seal	LH 1	\$ 60.00	\$ 20.00 120.00
19	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00
SPECIAL NETT TOTAL :				\$ 420.00 1,910.00

NNX
NECV
NECV
NNX
NECV
NNX
NECV
NNX
NNX
NNX
NNX
NNX
NNX
NNX
NNX
NNX
NECV
NECV
SCV

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R rear bumper reverse sensor	\$ 60.00 100.00
4	Check wiring	\$ 20.00 100.00
5	Upholstery	\$ 300.00
6	Diagnostic reset fault code	\$ 300.00
7	Panel beating	\$ 800.00 1,600.00
8	Rust proofing	\$ 200.00
9	Spray painting	\$ 600.00 1,600.00
LABOUR TOTAL :		\$ 1680.00 4,600.00

Survey
5/10/2021
Terrain
1530 hrs

Resurvey
6/10/2021
1520 hrs
Terrain

Part by Part repair
Repair days 6

PARTS TOTAL : \$ 9,495.38
SPECIAL NETT TOTAL : \$ 1,910.00
LABOUR TOTAL : \$ 4,600.00
GRAND TOTAL : \$ 16,005.38

Parts 3878.23
SN 420.00
Labour 1680.00
5978.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cor 5950.00 Part by Part