

Submit to insurance.

Not Authorized
Lhe

5/10/21

1/3 \$ 6000

the photo attached
5 days.

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

190 CLEMENCEAU AVE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

SKS3767X

ESTIMATE

DATE : 05/10/2021

VEHICLE NO : SJK3273H

MAKE/MODEL : TOYOTA WISH

ACC DATE : 04/10/2021

PARTICULAR

QTY	LIST PRICE	UNIT PRICE	AMOUNT	
			SS	SS
1	1 TAILGATE <i>badly DD</i>	\$ 1,477.60	1,477.60	✓
2	1 TAILGATE GLASS <i>11</i>	\$ 1,089.10	1,089.10	X
3	1 (SET) TAILGATE GLASS MOULDING <i>neu 188.20</i>	\$ 297.54	297.54	✓
4	1 TAILGATE CHROME MOULDING <i>sent/cro</i>	\$ 383.75	383.75	✓
5	1 TAILGATE LOGO <i>neu</i>	\$ 68.60	68.60	✓
6	1 TAILGATE STICKER "AERO TOURER" <i>neu</i>	\$ 96.10	96.10	✓
7	2 TAILGATE LICENCE LAMPS <i>11</i>	\$ 48.60	97.20	X
8	1 TAILGATE INNER LOCK <i>DD/Jm 416.60</i>	\$ 497.54	497.54	✓
9	1 TAILGATE INNER TRIM BOARD <i>de/cro</i>	\$ 481.60	481.60	✓
10	1 TAILGATE INNER PULL POCKET <i>11</i>	\$ 89.95	89.95	X
11	1 TAILGATE WIPER MOTOR <i>11</i>	\$ 521.60	521.60	X
12	1 TAILGATE weatherstrip <i>twi</i>	\$ 274.63	274.63	✓
13	2 TAILGATE DAMPER RH/LH <i>11</i>	\$ 182.60	365.20	X
14	2 TAILGATE HINGES RH/LH <i>11</i>	\$ 55.60	111.20	X
15	2 TAILGATE STOPPER <i>11</i>	\$ 10.50	21.00	X
16	2 TAILLAMP RH/LH <i>ms cro 408.10</i>	\$ 483.35	966.70	1PC
17	4 TAILLAMP SIDE CLIPS RH/LH <i>11</i>	\$ 10.50	42.00	X
18	1 REAR BUMPER <i>DD 596.90</i>	\$ 660.90	660.90	✓
19	2 REAR BUMPER REFLECTOR RH/LH <i>ms cro</i>	\$ 110.20	220.40	1PC
20	2 REAR BUMPER BRACKETSS RH/LH <i>11</i>	\$ 89.90	179.80	X
21	2 REAR BUMPER SIDE RETAINERS RH/LH <i>neu</i>	\$ 68.85	137.70	✓
22	1 REAR END PANEL <i>DD/sent 619.20</i>	\$ 781.90	781.90	✓
23	1 REAR END PANEL INNER MEMBER <i>11</i>	\$ 541.60	541.60	X
24	1 REAR END PANEL GARNISH <i>twi</i>	\$ 291.93	291.93	✓
25	1 REAR FLOOR BOARD <i>top one</i>	\$ 490.60	490.60	✓
26	2 REAR FENDER INNER TRIM BOARDS RH/LH <i>ms turn</i>	\$ 891.63	1,783.26	1PC
			\$ 11,969.40	
LESS - 25%			\$ 2,992.35	
TOTAL			\$ 8,977.05	

LEE BROTHERS AUTOMOTIVE PTE. LTD.

SPECIAL NETT ITEMS

1	1	(SET) TAILGATE GLASS SEALANT <i>net</i>	\$	80.00	<i>40</i>
2	1	(SET) TAILGATE GLASS FOAM TAPE <i>net</i>	\$	65.00	<i>30</i>
3	1	(SET) REAR BUMPER CLIP <i>net</i>	\$	35.00	<i>✓</i>
4	1	(SET) REAR REVERSE SENSOR <i>Shred</i>	\$	280.00	<i>200</i>
5	1	REAR REVERSE CAMERA <i>11</i>	\$	450.00	<i>X</i>
6	1	(SET) NUMBER PLATE WITH HOLDER <i>sent</i>	\$	60.00	<i>40</i>
TOTAL			\$	970.00	

LABOUR CHARGES :

LABOUR CHARGES :				
1	TO CHECK REAR ELECTRICAL WIRING	\$	50.00	20
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	\$	120.00	80
3	TO REMOVE, REFIX TAILGATE GLASS AND PERFORM WATER TEST	\$	180.00	120
4	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	\$	100.00	50
5	TO RESPRAY UNDERCOATING	\$	120.00	60
6	TO TRANSFER AND REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	\$	150.00	60
7	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	1,200.00	1050
8	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	1,200.00	800
		\$	3,120.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,067.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-65844.01
252
P-4938-05
S-N-345
L 2240
7523-48
202
6/18