

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0812/2021/JT
DATE : 4-Oct-21
WIP : 47364

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : TANG BUCK KIAU
ADDRESS : 2 KENINGSTON PARK DRIVE
#02-04
SINGAPORE 557320
TELEPHONE : HP +65 96637850
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210019767
VEHICLE NO : **SLD 6572 M**
MODEL CODE : A5 SB 2.0 TFSI S
MODEL YEAR : 25/2/2021
ENGINE NO : DEM 028524
CHASSIS NO : WAUZZF52MA018405
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Oct-21
PLACE OF ACCIDENT : JUNCTION OF EAST COAST
ROAD AND STILL ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 6572 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM . TO CARRY OUT VACUUM AND REGAS.(R1234)	S/N \$ 2,000.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. REINSTALL ALL PARTS RMOVED	\$ 4,800.00	1000
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,372.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,342.00	✓	
2	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 71.00	?	
3	FRONT BUMPER LOWER GRILLE <i>crushed</i>	1	\$ 195.00	✓	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 262.00	?	
5	FRONT BUMPER SPOILER <i>?</i>	1	\$ 535.00	?	
6	FRONT BUMPER AIR GUIDE - RH <i>Missing</i>	1	\$ 63.00	✓	
7	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$ 262.00	?	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	1	\$ 135.00	✓	
9	FRONT BUMPER TRIM - RH <i>Dist</i>	1	\$ 48.00	✓	
10	FRONT BUMPER TRIM - CENTER <i>?</i>	1	\$ 114.00	?	
11	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,694.00	✓	
12	FOAM FILLER PIECE <i>?</i>	1	\$ 146.00	?	
13	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 845.00	?	
14	FRONT BUMPER BRACKET - RH <i>?</i>	1	\$ 214.00	?	
15	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 36.00	✓	
16	FRONT BUMPER TOP COVER - RH <i>?</i>	1	\$ 127.00	?	
17	"CAUTION" STICKER <i>?</i>	1	\$ 14.00	?	
18	"A/c" STICKER <i>?</i>	1	\$ 8.00	?	
19	LOCK CARRIER BRACKET <i>crushed</i>	1	\$ 137.00	✓	
20	LOCK CARRIER SUPPORT BRACKET <i>?</i>	1	\$ 58.00	?	
SUB TOTAL SPARE PARTS		:	\$ 7,306.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN - RH <i>Neu</i>	1	\$ 126.00	+	
22	HORN BRACKET - RH <i>Neu</i>	1	\$ 29.00	+	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>Outer Missing</i>	2	TBC	/ 2	
24	FRONT PARKING AID SENSOR SEAL RING ?	4	\$ 9.00	?	
25	FRONT BUMPER WIRING SET <i>Neu</i>	1	\$ 405.00	+	
26	FRONT FENDER - RH <i>Buckled</i>	1	\$ 1,060.00	✓	
27	FRONT FENDER ATTACHMENT PARTS - RH <i>Neu</i>	1	\$ 35.00	+	
28	FRONT FENDER BRACE - RH ?	1	\$ 118.00	?	
29	FRONT FENDER TRIM - RH <i>Neu</i>	1	\$ 164.00	✓	
30	FRONT WHEEL HOUSING LINER - RH ?	1	\$ 275.00	?	
31	FRONT WHEEL SPOILER - RH <i>Cracked</i>	1	\$ 169.00	✓	
32	FRONT WHEEL SPOILER TRIM - RH ?	1	\$ 36.00	?	
33	LED HEADLIGHT - RH <i>Neu</i>	1	\$ 7,685.00	+	
34	LIFT CYLINDER - RH ?	1	\$ 198.00	?	
35	LIFT CYLINDER PIPE - RH <i>Neu</i>	1	\$ 198.00	+	
36	LOCK CARRIER <i>Neu</i>	1	\$ 1,016.00	+	
37	LOCK CARRIER LOWER SUPPORT - RH <i>Neu</i>	1	\$ 38.00	+	
38	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Neu</i>	1	\$ 19.00	+	
39	A/C CONDENSOR <i>?</i>	1	\$ 622.00	+	
40	AIR CHARGE COOLER <i>?</i>	1	\$ 587.00	+	
SUB TOTAL SPARE PARTS		:	\$ 12,789.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	CHARGE AIR COOLER PRESSURE HOSE - RH <i>new</i>	1	\$ 357.00	<i>+</i>
42	RADIATOR <i>new</i>	1	\$ 904.00	<i>+</i>
43	RADIATOR AIR GUIDE - RH <i>?</i>	1	\$ 32.00	<i>+</i>
44	RADIATOR AIR GUIDE - RH <i>?</i>	1	\$ 16.00	<i>?</i>
45	RADIATOR AIR GUIDE - UPPER <i>?</i>	1	\$ 16.00	<i>?</i>
46	RADIATOR AIR GUIDE - LOWER <i>?</i>	1	\$ 22.00	<i>?</i>
47	RADIATOR COOLANT <i>new</i>	6	\$ 267.00	<i>+</i>
48	FRONT NO PLATE <i>Deleted</i>	S/N	\$ 60.00	<i>✓</i>
49	SUNDRIES <i>?</i>	1	\$ 350.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 22,119.00	
TOTAL LABOUR CHARGES		:	\$ 10,372.00	
GRAND TOTAL		:	\$ 32,491.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lj
04/10/21

Not Authorised, 04 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT