

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Denise .

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0812/2021/JT

7-Oct-21

CHANG

1 of 1

SLD 6572 M

AUDI A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER CLOSING ELEMENT - RH <i>Painted Bent</i>	\$ 74.00	✓
2	FRONT FENDER BRACKET - RH <i>Bent Bent</i>	\$ 35.00	✓
3	FRONT FENDER RIVET SET <i>re</i>	\$ 33.00	✓
4	FRONT FENDER TOP LEDGE COVER - RH OUTER <i>Painted</i>	\$ 16.00	✓
5	FRONT FENDER TOP LEDGE COVER - RH INNER	\$ 36.00	✓
6	HEADLIGHT - RH <i>covers</i> <i>Painted</i>	\$ 44.00	✓
GRAND TOTAL		\$ 238.00	

For Premium Automobiles Pte Ltd

Adrian Ling
#888 08/10/21



Authorised Signature

Car-in

7/10/21

wip: 47364

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



LQ/Hang

AIR- Adrian

4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	S 2,342.00	✓
2	FRONT BUMPER SECURING STRIP Missing	2	S 71.00	✓
3	FRONT BUMPER LOWER GRILLE Cracked	1	S 195.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE Cracked	1	S 262.00	✓
5	FRONT BUMPER SPOILER	1	S 535.00	?
6	FRONT BUMPER AIR GUIDE - RH Missing	1	S 63.00	✓
7	FRONT BUMPER CLOSING ELEMENT	1	S 262.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - RH Missing	1	S 135.00	✓
9	FRONT BUMPER TRIM - RH Cracked	1	S 48.00	?
10	FRONT BUMPER TRIM - CENTER	1	S 114.00	?
11	RADIATOR GRILLE Cracked	1	S 1,694.00	✓
12	FOAM FILLER PIECE	1	S 146.00	?
13	FRONT BUMPER REINFORCEMENT BEAM	1	S 845.00	?
14	FRONT BUMPER BRACKET - RH	1	S 214.00	?
15	FRONT BUMPER GUIDE SECTION - RH	1	S 36.00	✓
16	FRONT BUMPER TOP COVER - RH	1	S 127.00	?
17	"CAUTION" STICKER	1	S 14.00	?
18	"A/c" STICKER	1	S 8.00	?
19	LOCK CARRIER BRACKET Cracked	1	S 137.00	✓
20	LOCK CARRIER SUPPORT BRACKET	1	S 58.00	?

SUB TOTAL SPARE PARTS

: \$ 7,306.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	HORN - RH <i>new</i>	1	S	126.00	x	
22	HORN BRACKET - RH <i>new</i>	1	S	29.00	x	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>could be used</i>	2	TBC	12.00	/ 2	
24	FRONT PARKING AID SENSOR SEAL RING ?	4	S	9.00	?	
25	FRONT BUMPER WIRING SET <i>new</i>	1	S	405.00	x	
26	FRONT FENDER - RH <i>Bruckled</i>	1	S	1,060.00	✓	
27	FRONT FENDER ATTACHMENT PARTS - RH <i>new</i>	1	S	35.00	x	
28	FRONT FENDER BRACE - RH <i>Best</i>	1	S	118.00	✓	
29	FRONT FENDER TRIM - RH <i>new</i>	1	S	164.00	✓	
30	FRONT WHEEL HOUSING LINER - RH	1	S	275.00	?	
31	FRONT WHEEL SPOILER - RH <i>could</i>	1	S	169.00	✓	
32	FRONT WHEEL SPOILER TRIM - RH <i>could</i>	1	S	36.00	✓	
33	LED HEADLIGHT - RH <i>new could</i>	1	S	7,685.00	x	
34	LIFT CYLINDER - RH	1	S	198.00	?	
35	LIFT CYLINDER PIPE - RH <i>new</i>	1	S	198.00	x	
36	LOCK CARRIER <i>new</i>	1	S	1,016.00	x	
37	LOCK CARRIER LOWER SUPPORT - RH <i>new</i>	1	S	38.00	x	
38	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	S	19.00	x	
39	A/C CONDENSOR <i>new</i>	1	S	622.00	x	
40	AIR CHARGE COOLER <i>new</i>	1	S	587.00	x	
SUB TOTAL SPARE PARTS			:	\$	12,789.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408695
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 6572 M

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
41	CHARGE AIR COOLER PRESSURE HOSE - RH <i>New</i>	1	S	357.00	<i>x</i>
42	RADIATOR <i>New</i>	1	S	904.00	<i>x</i>
43	RADIATOR AIR GUIDE - RH <i>checked</i>	1	S	32.00	<i>✓</i>
44	RADIATOR AIR GUIDE - RH <i>?</i>	1	S	16.00	<i>?</i>
45	RADIATOR AIR GUIDE - UPPER <i>?</i>	1	S	16.00	<i>?</i>
46	RADIATOR AIR GUIDE - LOWER <i>?</i>	1	S	22.00	<i>?</i>
47	RADIATOR COOLANT <i>New</i>	6	S	267.00	<i>x</i>
48	FRONT NO PLATE <i>Desired</i>	S/N	S	60.00	<i>✓</i>
49	SUNDRIES <i>?</i>	1	S	350.00	<i>?</i>
TOTAL SPARE PARTS		:	\$	22,119.00	
TOTAL LABOUR CHARGES		:	\$	10,372.00	
GRAND TOTAL		:	\$	32,491.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.