

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010272/KES3Q2**Date:** 11/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900100753
Claimant Vehicle No :	SMX5283L	Insured Vehicle No :	SKM3959R
Date of Loss:	03/10/2021	Nature of Claim:	TP
		Claim No:	3741026038SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX5283L	Engine No:	27492030522717
Make & Model:	MERCEDES-BENZ E200, 2.0 (A)	Chassis No:	WDD2120342B267264
Reg. Date:	01/03/2016 (Man. Year: 2015)	Odometer:	119270 km
Colour:	Metallic Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	265/35Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,845.60	3,265.70	579.90	15.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	575.00	1,125.00	66.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,545.60	3,840.70	1,704.90	30.74
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,545.60	3,050.00	2,495.60	45.00
+ GST 7.00/7.00% (S\$)	388.19	213.50	174.69	45.00
Nett Amount (S\$)	5,933.79	3,263.50	2,670.29	45.00
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,565.50		

INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	05/10/2021	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,920.00 FL	*1,712.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	58.00 FL	*- FL
3	1		*REAR BUMPER INNER GUIDE LH	Cracked	66.00 FL	*66.00 FL
4	1		*REAR BUMPER LOWER DIFFUSER	Scratched / Cut	340.00 FL	*340.00 FL
5	1		*REAR BUMPER LOWER CHROME MOULDING	Mtg Cracked	470.00 FL	*218.00 FL
6	1		*REAR EXHAUST CHROME TIP LH	Dented	330.00 FL	*287.00 FL
7	1		*REAR TAIL LAMP LH	Mtg Cracked	700.00 FL	*700.00 FL
8	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR BOOTLID (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*225.00 FS
					Sub Total (\$)	4,234.00 3,598.00
					- List Item Discount on L Items 10.00/10.00% (\$)	388.40 332.30
					Total Parts (\$)	3,845.60 3,265.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR BOOTLID ,REAR END PANEL & ETC	New	700.00	250.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	60.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
Gross Labour Cost (\$)			1,700.00	575.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >