

Date: 05/10/2021

Vehicle No: SMX5283L

Model: MERCEDES BENZ E200 SEDAN

Chassis: WDD2120342B267264-2015

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: SKM3959R

Date of Accident: 03/10/2021

Estimator: TING AN

Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                       | QTY | UNIT S\$ | AMOUNT S\$            |
|-------------|-----------------------------------|-----|----------|-----------------------|
| 1           | REAR BUMPER                       | 1   |          | <i>R</i> \$1,920.00   |
| 2           | REAR BUMPER SIDE RETAINER LH      | 1   |          | <i>L</i> \$58.00      |
| 3           | REAR BUMPER INNER GUIDE LH        | 1   |          | \$66.00               |
| 4           | REAR BUMPER LOWER DIFFUSER        | 1   |          | <i>P/R/L</i> \$340.00 |
| 5           | REAR BUMPER LOWER CHROME MOULDING | 1   |          | \$470.00              |
| 6           | REAR EXHUAUST CRHOME TIP LH       | 1   |          | \$330.00              |
| 7           | REAR TAIL LAMP LH                 | 1   |          | \$700.00              |
| 8           | REAR END PANEL                    | 1   |          | REPAIR                |
| 9           | REAR BOOTLID                      | 1   |          | REPAIR                |
| SUB TOTAL   |                                   |     |          | \$3,884.00            |
| LESS 10%    |                                   |     |          | -\$388.40             |
| PARTS TOTAL |                                   |     |          | \$3,495.60            |

| NO.       | SPECIAL NETT               | QTY | UNIT S\$ | AMOUNT S\$       |
|-----------|----------------------------|-----|----------|------------------|
| 1         | REAR BUMPER CLIPS          | 1   |          | <i>m</i> \$50.00 |
| 2         | REAR BUMPER REVERSE SENSOR | 1   |          | \$300.00         |
| S/N TOTAL |                            |     |          | \$350.00         |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00

*25cl*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR BOOTLID, REAR END PANEL & ETC.

\$700.00

*25cl*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00

*6cl*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$100.00

*7*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00

*15cl*

LABOUR TOTAL \$1,700.00

|               |                                                                         |       |            |
|---------------|-------------------------------------------------------------------------|-------|------------|
| VIC / TING AN | <b>LKK Auto Consultants hence notify the Repairer of the following:</b> | TOTAL | \$5,545.60 |
|---------------|-------------------------------------------------------------------------|-------|------------|

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items to be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Acknowledged by Repairer

Signature:

Date: