



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB82Z
Case Reference Number	BUS/09/21/5043
Registration Date	8/7/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	ABDUL KAMAR BIN HARUN
Type of Accident	Side Swipe
Accident Date and Time	28/9/2021 10:22 AM
Accident Reported Date and Time	28/9/2021 11:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112655
Special Instruction to ARC,if any	SMB82Z-FRONT RIGHT WINDSCREEN CRACKED AND RIGHT VIEW MIRROR DAMAGED EXCAVATOR (TP) INSURED WITH
Prepared Date and Time	6/10/2021 6:14 PM
Chassis Number	WEB63442021000201
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,240.00	\$3,710.00
Total Spray Cost	\$942.00	\$772.00
Total Spare Part Cost	\$9,063.99	\$9,063.99
Total Other Cost	\$200.00	\$200.00
TOTAL COST	\$14,445.99	\$13,745.99
Lump Sum Total	\$0.00	\$13,750.00
Number of Repair Days	10.0	9.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	15/10/2021 2:42 PM	20/10/2021 11:50 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$4,240.00				\$3,710.00	
Total Labour				\$4,240.00				\$3,710.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TO PUTTY & RESPRAY				\$942.00				\$772.00	
Total Spray Painting & Panel Beating				\$942.00				\$772.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TOWING CHARGE				\$200.00				\$200.00	
Total Other Costs				\$200.00				\$200.00	
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace
6009357	Body		PANEL,FRONT:FIBREGLASS,FOR MB OC500 BUS	1.00	\$3,105.00	10.00	\$2,794.50	Replace	Replace
6012673			MIRROR,VIEW:REAR,ELECTRICAL,RH,MBOC500	1.00	\$1,139.05	10.00	\$1,025.14	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	24.00	\$37.00	0.00	\$888.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
6009351	GLASS		WINDSCREEN,FRT:CENTRE,FOR MB OC500 BUS	1.00	\$6,210.00	10.00	\$5,589.00	Replace	Replace
6009353	GLASS		WINDSCREEN,FRT:R/H, FOR MB OC500 BUS	1.00	\$931.50	10.00	\$838.35	Replace	Replace
Total					\$11,617.55		\$11,329.99		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									