



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21010273/R1f3e2	
			Date: 30/11/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY		Veh. Inspected	SMB 82Z
Policy No.			Coverage (\$)	0.00
Claim No.	20/21/21/EC00/002274		Excess (\$)	0.00
Assign From	CHEW SHIN LING		Assign Date	05/10/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ OC500LE1830H		c.c	11967
Engine No.	HIDDEN		Year of Reg.	2009
Chassis No.	WEB63442021000201		Colour	GREEN
Odometer	878714 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FALKEN	8 mm	
L/H Front Tyre	275/70 R22.5	FALKEN	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FALKEN	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FALKEN	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2021		Inspection Date	15/10/2021
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	