

(08/11/13) wef

ASS. REC. BY: P. Khan

REF:

CS/LPC21016273/R1 f3

2920

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMB 822

Yr Regn:

2009 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MARENS BAZ 06500LE 1030 H.C 11967

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp.Reading

878714

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WEB6344 2021 000 261

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

D/P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

28/01/21

D.O.I.

13/10/21

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Finalised amount of \$ 13,750 / 9 days of lump sum repair is confirmed

RED: 3249.55;19%

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/10/2021


User ID : JeongCH

Section A - Accident Details

Registration Number	SMB82Z
Case Reference Number	BUS/09/21/5043
Registration Date	7/8/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	ABDUL KAMAR BIN HARUN
Type of Accident	Side Swipe
Accident Date and Time	9/28/2021 10:22 AM
Accident Reported Date and Time	9/28/2021 11:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112655
Special Instruction to ARC, if any	SMB82Z-FRONT RIGHT WINDSCREEN CRACKED AND RIGHT VIEW MIRROR DAMAGED EXCAVATOR (TP) INSURED WITH
Prepared Date and Time	10/6/2021 6:14 PM
Chassis Number	WEB63442021000201
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,240.00	\$0.00
Total Spray Cost	\$942.00	\$0.00
Total Spare Part Cost	\$9,312.39	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$14,694.39	\$0.00
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	9 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date		
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 7511
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/10/2021
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$4,240.00	3710
Total Labour	\$4,240.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$942.00	772
Total Spray Painting & Panel Beating	\$942.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	\$200.00	200
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	na
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	na
009357	Body		PANEL, FRONT: FIBREGLASS, FOR MB OC500 BUS	1.00	\$3,105.00	0.00	\$3,105.00	Replace	cm
009351	GLASS		WINDSCREEN, FRT: CENTRE, FOR MB OC500 BUS	1.00	\$6,210.00	10.00	\$5,589.00	Replace	cm
009353	GLASS		WINDSCREEN, FRT: R/H, FOR MB OC500 BUS	1.00	\$931.50	10.00	\$838.35	Replace	cm
012673			MIRROR, VIEW: REAR, ELECTRICAL, RH, MBOC500	1.00	\$1,139.05	10.00	\$1,025.14	Replace	cm
006314	CONSUMABLE		ADHESIVE: DIRECT GLAZING	24.00	\$37.00	0.00	\$888.00	Replace	na
006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	na
Total					\$11,617.55		\$11,640.49		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame
Hp 9001268

9 days

4/5

15/10/21 @ 1140

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	-
Date of Accident	28/09/2021 10:22 (SGT)
Exact Location of Accident	Aft Lim Chu Kang Lane 4, Singapore
Additional Location Information	LIM CHU KANG ROAD (BEFORE BS:34019, AFT LIM CHU KANG LANE 4)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB82Z
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SMRT BUSES LTD
Company Reg No	1XXXXX292D
Email Address	Auto-Svcs-BARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662672
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	MBOC500
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	11967

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097498MFBP
Cover Note Number	-

DRIVER

Name of Driver	HU XIAOYU
----------------	-----------

(Draft)

Passport No/FIN GXXXX479X
Date Of Birth 01/08/1990
Occupation Outdoor
Date Of Driving Pass 15/01/2019
Driving experience 2 YEARS AND 8 MONTHS
Gender Male
Mobile Number (Phone) +65-68662672
Alt. Phone Number -
Email Address Auto-Svcs-BARC@smrt.com.sg
Address 6 ANG MO KIO STREET 62
Address complement -
Postcode -
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Employee
Does Driver Own Other Vehicles? No
Vehicle Registration Number of Other Vehicle Owned by Driver -
Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

On 28/9/2021 at 1022 hrs, I was driving SMB82Z, Svc 975. I was travelling at 20-30 Km/Hr. There were 02 pax on board. I was travelling at along Lim Chu Kang Road. I was travelling on my lane and there was road work on the on coming lane. Due to the road work there was a temporary setup traffic light signal and it was green on my favor. I was slow down to pass by and there was only lorry on my right and I did not see the Excavator. When I pass by the arm of the excavator suddenly swung to the left and hit onto my bus Right front windscreen cracked. I stopped my bus and checked and my bus right front windscreen webbed and the RHS view mirror damaged. No visible damaged on the Excavator. There were no personnel injured due to this accident. I was travelling on my lane and was the excavator sudden swung out.

ATTACHMENT(S)

Are accident photos available for attachment? No
Was there any video captured by Car Camera? Yes
Reasons for not uploading a video of the accident PENDING DOWNLOAD
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EXCAVATOR
Vehicle Manufacturer -
Vehicle Model -

(Draft)

Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number

Address
Address complement

Postcode
Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

-
-
Commercial vehicle

MO GUAN CONSTRUCTION ENGINEERING PTE LTD

-
-
-
-
-
-
-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	292D
Vehicle No.:	SMB82Z
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	OC500LE1830H
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	45796600169272
Chassis No.:	WEB63442021000201
Maximum Power Output:	-
Open Market Value:	\$329,368.00
Original Registration Date:	08 Jul 2009
First Registration Date:	08 Jul 2009
Transfer Count:	0
Actual ARF Paid:	\$16,469.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 18 Oct 2021

OK