

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$52k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SKU 9118UType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HondaColour: M. P. WhiteSp. Reading: 109750

Eng/No: _____

C/No: RU1Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 29/9/21

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Date: 02/10/2021

Vehicle No: SKU9118U

Model: HONDA VEZEL 1.5X CVT

Chassis: RU11201447-2016

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: SMF6488B

Date of Accident: 29/09/2021

Estimator:

Surveyor:

TING AN

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		RM \$854.10
2	FRONT BONNET HINGE LH	1		RM \$50.00
3	FRONT BONNET HINGE RH	1		RM \$50.00
4	FRONT BONNET LOCK	1		RM \$126.10
5	FRONT GRILLE	1		CM \$329.20
6	FRONT GRILLE GARNISH COVER	1		CM \$222.40
7	FRONT GRILLE EMBLEM	1		RM \$30.50
8	FRONT GRILLE SUPPORT BRACKET LH	1		RM \$24.20
9	FRONT GRILLE SUPPORT BRACKET RH	1		\$24.20
10	FRONT GRILLE CENTER SUPPORT BRACKET	1		\$39.50
11	FRONT HEADLAMP LH	1		CM \$1,865.70
12	FRONT HEADLAMP RH	1		\$1,865.70
13	FRONT HEADLAMP LOWER BRACKET LH	1		CM \$34.20
14	FRONT HEADLAMP LOWER BRACKET RH	1		\$34.20
15	FRONT BUMPER	1		RM / RM \$898.30
16	FRONT BUMPER SIDE BRACKET LH	1		CM \$23.90
17	FRONT BUMPER SIDE BRACKET RH	1		CM \$23.90
18	FRONT BUMPER LOWER GRILLE	1		\$84.20
19	FRONT BUMPER LOWER LIP COVER	1		RM \$195.60
20	FRONT BUMPER TOWING COVER	1		RM \$18.30
21	FRONT BUMPER FOG LAMP LH	1		\$255.70
22	FRONT BUMPER FOG LAMP RH	1		RM \$255.70
23	FRONT BUMPER FOG LAMP GARNISH COVER LH	1		\$41.70
24	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		RM \$41.70
25	FRONT AIR DEFLECTOR LH	1		CM \$44.90
26	FRONT AIR DEFLECTOR RH	1		\$44.90
27	FRONT BUMPER REINFORCEMENT	1		RM \$293.40
28	FRONT BUMPER REINFORCEMENT EXTENTION PANEL LH	1		\$128.70
29	FRONT SUPPORT PANEL	1		RM \$548.20
30	FRONT SUPPORT PANEL TOP COVER	1		RM \$56.10
31	FRONT INTAKE AIR DUCT	1		RM \$78.70
32	FRONT AIR INTAKE TUBE	1		RM \$47.60
33	FRONT AIR RESONATOR BOX	1		CM \$152.00
34	FRONT HORN	1		\$82.70
35	FRONT TEMPERATURE SENSOR	1		\$46.30
36	FRONT BATTERY CASING	1		\$37.50
37	FRONT FENDER LH	1		RM \$421.10

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/10/2021
Vehicle No: SKU911SU
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

38	FRONT FENDER RH	1		R	\$421.10	X
39	FRONT FENDER INNER SHIELD LH	1		Div	\$112.30	✓
40	FRONT FENDER INNER SHIELD RH	1		Plu	\$112.30	X
41	FRONT FENDER WHEEL ARCH COVER LH	1		Plu	\$163.80	✓
42	FRONT FENDER WHEEL ARCH COVER RH	1			\$163.80	?
43	FRONT FENDER INNER PANEL LH	1			\$107.70	?
44	FRONT FENDER OUTER PANEL LH	1		Ry	\$96.10	✓
45	FRONT AIRCON CONDENSER	1			\$817.50	?
46	FRONT AIRCON CONDENSER PRESSURE PIPE	1			\$180.70	?
47	FRONT AIRCON CONDENSER LIQUID TUBE	1			\$174.60	?
48	FRONT RADIATOR	1			\$1,330.40	?
49	FRONT RADIATOR TOP HOSE	1		Plu	\$30.60	X
50	FRONT RADIATOR BOTTOM HOSE	1			\$33.20	?
51	FRONT RADIATOR FAN SHROULD LH	1			\$123.60	?
52	FRONT RADIATOR FAN SHROULD RH	1			\$116.80	?
53	FRONT RADIATOR FAN BLADE LH	1			\$67.70	?
54	FRONT RADIATOR FAN BLADE RH	1			\$70.20	?
55	FRONT RADIATOR FAN MOTOR LH	1			\$322.80	?
56	FRONT RADIATOR FAN MOTOR RH	1			\$315.30	?
57	FRONT WINDSCREEN GLASS	1		CM	\$1,812.70	✓
58	FRONT WINDSCREEN MOULDING	1		Plu	\$107.90	✓
59	FRONT DASHBOARD AIRBAG	1		Plu	\$2,236.80	✓
60	FRONT DASHBOARD	1		Plu	\$1,746.10	✓
61	FRONT STEERING WHEEL AIRBAG	1		Plu	\$1,640.30	✓
62	B-PILLAR GARNISH COVER LH	1			\$84.80	?
63	B-PILLAR GARNISH COVER RH	1			\$84.80	?
64	FRONT SAFETY BELT LH	1		Plu	\$585.10	✓
65	FRONT SAFETY BELT RH	1		Plu	\$585.10	✓
66	AIRBAG CONTROL UNIT	1		Plu	\$1,066.90	✓
67	FRONT AIRBAG IMPACT SENSOR LH	1		Plu	\$184.30	✓
68	FRONT AIRBAG IMPACT SENSOR RH	1		Plu	\$184.30	✓
69	FRONT DOOR LH	1			REPAIR	✓
70	FRONT DOOR RH	1			REPAIR	✓
SUB TOTAL					\$24,450.70	
LESS 20%					-\$4,890.14	
PARTS TOTAL					\$19,560.56	

Date: 02/10/2021
Vehicle No: SKU911SU
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		Ne \$40.00
2	FRONT BUMPER CLIPS	1		Ne \$50.00
3	FRONT NUMBER PLATE	1		CM \$40.00
4	FRONT NUMBER PLATE HOLDER	1		\$40.00
5	FRONT SUPPORT TOP COVER CLIPS	1		Ne \$30.00
6	FRONT BATTERY	1		Ne \$250.00
7	FRONT FENDER INNER SHIELD CLIPS LH	1		Ne \$40.00
8	FRONT FENDER INNER SHIELD CLIPS RH	1		\$40.00
9	FRONT WINDSCREEN SEALANT	1		Ne \$80.00
10	FRONT RADIATOR COOLANT	1		Ne \$60.00
S/N TOTAL				\$670.00

—
—
} 85m
—
500m
—
400m
400m

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,400.00 900

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

\$1,400.00 1200

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.

\$300.00 250

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, STEERING WHEEL AIRBAG, FRONT DASHBOARD AIRBAG & ETC.

\$400.00 200

TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.

\$300.00 220

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 120

Head office
8 Kung Chong Road Singapore 150143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554505
Tel (+65) 6494 9919 | Fax (+65) 6494 9931

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 02/10/2021
Vehicle No: SKU9118U
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

TO REFILL AIRCON GAS.	\$80.00	✓
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	120/
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	30/

LABOUR TOTAL	\$4,480.00
--------------	------------

TING AN

TOTAL	\$24,710.56
-------	-------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 9919 | Fax (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011





SINGAPORE POLICE FORCE



T/20210929/7017

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210929/7017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/09/2021 17:17	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: CHENG HUP KERN			Address: 325B SUMANG WALK #21-955 SINGAPORE 822325		
ID Type / ID No.: NRIC NO / S7611959G			Contact No.: Home/Office: Mobile: 91121333		
Nationality: SINGAPORE CITIZEN			Email: NIGELLUCIFER@HOTMAIL.COM		
Sex: Male	Age: 45	Date of Birth: 25/04/1976	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Personal Driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 29/09/2021 13:00	Type of Location: X-Junction
Location: ESPLANADE DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic
Type of Collision: X-Junction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SKU9118U	Car	HONDA	Vezel			0
SMF6488B	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20210929/7017

2 of 3

Report No. T/20210929/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	CHENG HUP KERN	ID No.	S7611959G
Related Vehicle	SKU9118U (Car)	Contact No.	91121333
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	29/09/2021	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	Serious
Driver			
Name	ZHANG YU GANG	ID No.	S84864230
Related Vehicle	SMF6488B (Car)	Contact No.	98897297
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 29/09/2021 at about 1300 hrs, I was driving my vehicle A: SKU9118 along Esplanade Drive. Suddenly, I felt an impact on my front left, I immediately blacked out. After a few minutes, I regained consciousness and was conveyed in an ambulance to the hospital. The other party driver took my contact number when I was in the ambulance. After being discharged, I contacted the other party and got hold of his car plate number: SMF6488B.