

ASS. REC. BY:

REF:

A/G / 210102751ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

5/11 21:15 @ 16,750L Carson

Veh No:

SKU 9118U Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Verel c.c. 1896

Colour

M.P. White A/C: Insured / Std / NI / NA

Sp. Reading

109750 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUI 1201847

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Nexen

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

29/9/21

D.O.I.

4/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

Date: 02/10/2021

Vehicle No: SKU9118U

Model: HONDA VEZEL 1.5X CVT

Chassis: RU11201447-2016

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: SMF6488B

Date of Accident: 29/09/2021

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		854.10
2	FRONT BONNET HINGE LH	1		50.00
3	FRONT BONNET HINGE RH	1		50.00
4	FRONT BONNET LOCK	1		126.10
5	FRONT GRILLE	1		329.20
6	FRONT GRILLE GARNISH COVER	1		222.40
7	FRONT GRILLE EMBLEM	1		30.50
8	FRONT GRILLE SUPPORT BRACKET LH	1		24.20
9	FRONT GRILLE SUPPORT BRACKET RH	1		24.20
10	FRONT GRILLE CENTER SUPPORT BRACKET	1		39.50
11	FRONT HEADLAMP LH	1		1,865.70
12	FRONT HEADLAMP RH	1		1,865.70
13	FRONT HEADLAMP LOWER BRACKET LH	1		34.20
14	FRONT HEADLAMP LOWER BRACKET RH	1		34.20
15	FRONT BUMPER	1		898.30
16	FRONT BUMPER SIDE BRACKET LH	1		23.90
17	FRONT BUMPER SIDE BRACKET RH	1		23.90
18	FRONT BUMPER LOWER GRILLE	1		84.20
19	FRONT BUMPER LOWER LIP COVER	1		195.60
20	FRONT BUMPER TOWING COVER	1		18.30
21	FRONT BUMPER FOG LAMP LH	1		255.70
22	FRONT BUMPER FOG LAMP RH	1		255.70
23	FRONT BUMPER FOG LAMP GARNISH COVER LH	1		41.70
24	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		41.70
25	FRONT AIR DEFLECTOR LH	1		44.90
26	FRONT AIR DEFLECTOR RH	1		44.90
27	FRONT BUMPER REINFORCEMENT	1		293.40
28	FRONT BUMPER REINFORCEMENT EXTENTION PANEL LH	1		128.70
29	FRONT SUPPORT PANEL	1		548.20
30	FRONT SUPPORT PANEL TOP COVER	1		56.10
31	FRONT INTAKE AIR DUCT	1		78.70
32	FRONT AIR INTAKE TUBE	1		47.60
33	FRONT AIR RESONATOR BOX	1		152.00
34	FRONT HORN	1		82.70
35	FRONT TEMPERATURE SENSOR	1		46.30
36	FRONT BATTERY CASING	1		37.50
37	FRONT FENDER LH	1		421.10

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



8708.40

Date: 02/10/2021
 Vehicle No: SKU9118U
 Model: HONDA VEZEL 1.5X CVT
 Chassis: RU11201447-2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMF6488B
 Date of Accident: 29/09/2021
 Estimator: TING AN
 Surveyor:

38	FRONT FENDER RH	1		R	\$421.10
39	FRONT FENDER INNER SHIELD LH	1		D-1	\$112.30
40	FRONT FENDER INNER SHIELD RH	1		Pu	\$112.30
41	FRONT FENDER WHEEL ARCH COVER LH	1		Bu	\$163.80
42	FRONT FENDER WHEEL ARCH COVER RH	1		my car	\$163.80
43	FRONT FENDER INNER PANEL LH	1		B1	\$107.70
44	FRONT FENDER OUTER PANEL LH	1		B1	\$96.10
45	FRONT AIRCON CONDENSER	1	730.80	R1	\$817.50
46	FRONT AIRCON CONDENSER PRESSURE PIPE	1		nd	\$180.70
47	FRONT AIRCON CONDENSER LIQUID TUBE	1		nd	\$174.60
48	FRONT RADIATOR	1	987.90	77/Pu	\$1,330.40
49	FRONT RADIATOR TOP HOSE	1		su	\$30.60
50	FRONT RADIATOR BOTTOM HOSE	1		su	\$33.20
51	FRONT RADIATOR FAN SHROULD LH	1		CM	\$123.60
52	FRONT RADIATOR FAN SHROULD RH	1		CM	\$116.80
53	FRONT RADIATOR FAN BLADE LH	1		CM	\$67.70
54	FRONT RADIATOR FAN BLADE RH	1		su	\$70.20
55	FRONT RADIATOR FAN MOTOR LH	1		Tu	\$322.80
56	FRONT RADIATOR FAN MOTOR RH	1		su	\$315.30
57	FRONT WINDSCREEN GLASS	1	1483	CM	\$1,812.70
58	FRONT WINDSCREEN MOULDING	1		su	\$107.90
59	FRONT DASHBOARD AIRBAG	1	2236.80	pu	\$2,236.80
60	FRONT DASHBOARD	1	1430	Tu	\$1,746.10
61	FRONT STEERING WHEEL AIRBAG	1	1640.30	Bu	\$1,640.30
62	B-PILLAR GARNISH COVER LH	1		my Di's	\$84.80
63	B-PILLAR GARNISH COVER RH	1		my Di's	\$84.80
64	FRONT SAFETY BELT LH	1		Tu	\$585.10
65	FRONT SAFETY BELT RH	1		Tu	\$585.10
66	AIRBAG CONTROL UNIT	1		su	\$1,066.90
67	FRONT AIRBAG IMPACT SENSOR LH	1		su	\$184.30
68	FRONT AIRBAG IMPACT SENSOR RH	1		su	\$184.30
69	FRONT DOOR LH	1			REPAIR
70	FRONT DOOR RH	1			REPAIR

SUB TOTAL	\$24,450.70
LESS 20%	-\$4,890.14
PARTS TOTAL	\$19,560.56

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 566047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



1295140

Date: 02/10/2021
Vehicle No: SKU9118U
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		40.00
2	FRONT BUMPER CLIPS	1		50.00
3	FRONT NUMBER PLATE	1		40.00
4	FRONT NUMBER PLATE HOLDER	1		40.00
5	FRONT SUPPORT TOP COVER CLIPS	1		30.00
6	FRONT BATTERY	1	1250W	250.00
7	FRONT FENDER INNER SHIELD CLIPS LH	1		40.00
8	FRONT FENDER INNER SHIELD CLIPS RH	1		40.00
9	FRONT WINDSCREEN SEALANT	1		80.00
10	FRONT RADIATOR COOLANT	1		60.00
S/N TOTAL				\$670.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,400.00 900

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

\$1,400.00 1200

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASBOARD & ETC.

\$300.00 250

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, STEERING WHEEL AIRBAG, FRONT DASHBOARD AIRBAG & ETC.

\$400.00 200

TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.

\$300.00 220

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 120

Head office

6 Jang Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 5546

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1983

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 02/10/2021
Vehicle No: SKU9118U
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

TO REFILL AIRCON GAS.	\$80.00	✓
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	120%
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	30%

LABOUR TOTAL	\$4,480.00
--------------	------------

TING AN	TOTAL	\$24,710.56
---------	-------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

