

Date: 02/10/2021

Vehicle No: SKU9118U

Model: HONDA VEZEL 1.5X CVT

Chassis: RU11201447-2016

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: SMF6488B

Date of Accident: 29/09/2021

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		RT \$854.10
2	FRONT BONNET HINGE LH	1		DIY \$50.00
3	FRONT BONNET HINGE RH	1		DIY \$50.00
4	FRONT BONNET LOCK	1		DIY \$126.10
5	FRONT GRILLE	1		CM \$329.20
6	FRONT GRILLE GARNISH COVER	1		CM \$222.40
7	FRONT GRILLE EMBLEM	1		ME \$30.50
8	FRONT GRILLE SUPPORT BRACKET LH	1		RT \$24.20
9	FRONT GRILLE SUPPORT BRACKET RH	1		\$24.20
10	FRONT GRILLE CENTER SUPPORT BRACKET	1		\$39.50
11	FRONT HEADLAMP LH	1		CM \$1,865.70
12	FRONT HEADLAMP RH	1		\$1,865.70
13	FRONT HEADLAMP LOWER BRACKET LH	1		CM \$34.20
14	FRONT HEADLAMP LOWER BRACKET RH	1		\$34.20
15	FRONT BUMPER	1		RT/TA \$898.30
16	FRONT BUMPER SIDE BRACKET LH	1		CM \$23.90
17	FRONT BUMPER SIDE BRACKET RH	1		CM \$23.90
18	FRONT BUMPER LOWER GRILLE	1		\$84.20
19	FRONT BUMPER LOWER LIP COVER	1		DIY \$195.60
20	FRONT BUMPER TOWING COVER	1		SM \$18.30
21	FRONT BUMPER FOG LAMP LH	1		\$255.70
22	FRONT BUMPER FOG LAMP RH	1		SM \$255.70
23	FRONT BUMPER FOG LAMP GARNISH COVER LH	1		\$41.70
24	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		SM \$41.70
25	FRONT AIR DEFLECTOR LH	1		CM \$44.90
26	FRONT AIR DEFLECTOR RH	1		\$44.90
27	FRONT BUMPER REINFORCEMENT	1		RT \$293.40
28	FRONT BUMPER REINFORCEMENT EXTENTION PANEL LH	1		\$128.70
29	FRONT SUPPORT PANEL	1		RT \$548.20
30	FRONT SUPPORT PANEL TOP COVER	1		DIY \$56.10
31	FRONT INTAKE AIR DUCT	1		BU \$78.70
32	FRONT AIR INTAKE TUBE	1		DIY \$47.60
33	FRONT AIR RESONATOR BOX	1		CM \$152.00
34	FRONT HORN	1		\$82.70
35	FRONT TEMPERATURE SENSOR	1		\$46.30
36	FRONT BATTERY CASING	1		\$37.50
37	FRONT FENDER LH	1		RT \$421.10

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/10/2021
Vehicle No: SKU9118U
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

38	FRONT FENDER RH	1		12	\$421.10	X
39	FRONT FENDER INNER SHIELD LH	1		10/1	\$112.30	✓
40	FRONT FENDER INNER SHIELD RH	1		10/1	\$112.30	X
41	FRONT FENDER WHEEL ARCH COVER LH	1		10/1	\$163.80	✓
42	FRONT FENDER WHEEL ARCH COVER RH	1			\$163.80	?
43	FRONT FENDER INNER PANEL LH	1			\$107.70	?
44	FRONT FENDER OUTER PANEL LH	1		10/1	\$96.10	✓
45	FRONT AIRCON CONDENSER	1			\$817.50	?
46	FRONT AIRCON CONDENSER PRESSURE PIPE	1			\$180.70	?
47	FRONT AIRCON CONDENSER LIQUID TUBE	1			\$174.60	?
48	FRONT RADIATOR	1			\$1,330.40	?
49	FRONT RADIATOR TOP HOSE	1		10/1	\$30.60	X
50	FRONT RADIATOR BOTTOM HOSE	1			\$33.20	?
51	FRONT RADIATOR FAN SHROULD LH	1			\$123.60	?
52	FRONT RADIATOR FAN SHROULD RH	1			\$116.80	?
53	FRONT RADIATOR FAN BLADE LH	1			\$67.70	?
54	FRONT RADIATOR FAN BLADE RH	1			\$70.20	?
55	FRONT RADIATOR FAN MOTOR LH	1			\$322.80	?
56	FRONT RADIATOR FAN MOTOR RH	1			\$315.30	?
57	FRONT WINDSCREEN GLASS	1		CM	\$1,812.70	✓
58	FRONT WINDSCREEN MOULDING	1		10/1	\$107.90	✓
59	FRONT DASHBOARD AIRBAG	1		10/1	\$2,236.80	✓
60	FRONT DASHBOARD	1		10/1	\$1,746.10	✓
61	FRONT STEERING WHEEL AIRBAG	1		10/1	\$1,640.30	✓
62	B-PILLAR GARNISH COVER LH	1			\$84.80	?
63	B-PILLAR GARNISH COVER RH	1			\$84.80	?
64	FRONT SAFETY BELT LH	1		10/1	\$585.10	✓
65	FRONT SAFETY BELT RH	1		10/1	\$585.10	✓
66	AIRBAG CONTROL UNIT	1		10/1	\$1,066.90	✓
67	FRONT AIRBAG IMPACT SENSOR LH	1		10/1	\$184.30	✓
68	FRONT AIRBAG IMPACT SENSOR RH	1		10/1	\$184.30	✓
69	FRONT DOOR LH	1			REPAIR	
70	FRONT DOOR RH	1			REPAIR	
					SUB TOTAL	\$24,450.70
					LESS 20%	-\$4,890.14
					PARTS TOTAL	\$19,560.56

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/10/2021
 Vehicle No: SKU9118U
 Model: HONDA VEZEL 1.5X CVT
 Chassis: RU11201447-2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMF6488B
 Date of Accident: 29/09/2021
 Estimator: TING AN
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		1pc \$40.00
2	FRONT BUMPER CLIPS	1		1pc \$50.00
3	FRONT NUMBER PLATE	1		1cm \$40.00
4	FRONT NUMBER PLATE HOLDER	1		\$40.00
5	FRONT SUPPORT TOP COVER CLIPS	1		1pc \$30.00
6	FRONT BATTERY	1		1pc \$250.00
7	FRONT FENDER INNER SHIELD CLIPS LH	1		1pc \$40.00
8	FRONT FENDER INNER SHIELD CLIPS RH	1		\$40.00
9	FRONT WINDSCREEN SEALANT	1		1pc \$80.00
10	FRONT RADIATOR COOLANT	1		1pc \$60.00
S/N TOTAL				\$670.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,400.00 900

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

\$1,400.00 1200

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASBOARD & ETC.

\$300.00 250

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, STEERING WHEEL AIRBAG, FRONT DASHBOARD AIRBAG & ETC.

\$400.00 200

TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.

\$300.00 220

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 120

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/10/2021
Vehicle No: SKU9118U
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11201447-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMF6488B
Date of Accident: 29/09/2021
Estimator: TING AN
Surveyor:

TO REFILL AIRCON GAS.

\$80.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$200.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00

LABOUR TOTAL \$4,480.00

TING AN

TOTAL

\$24,710.56

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

