

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010281/AVCE2

Date: 12/11/2021

REFERENCE

Insured/Claimant:	CHEANG SIEW KAY	Policy No:	1900133311-01	
Date of Loss:	07/09/2021	Nature of Claim:	OD	Claim No: 9592700373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDD3939D		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK081608
Reg. Date:	31/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF44KA071451
Colour:	White	Odometer:	5061 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$126,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,599.00	5,892.40	6,706.60	53.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,282.00	2,932.00	3,350.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,881.00	8,824.40	10,056.60	53.26
- Excess (S\$)	100.00	100.00	0.00	0.00
(S\$)	18,781.00	8,724.40	10,056.60	53.55
+ GST 7.00/7.00% (S\$)	1,314.67	610.71	703.96	53.55
Nett Amount (S\$)	20,095.67	9,335.11	10,760.56	53.55

INSPECTION

Date of Assignment:	06/10/2021		
Date Inspected:	04/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	2,996.00 FS	*2,396.80 FS
2	1		*SET REAR BUMPER FIXING	Not Necessary	459.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Damaged	223.00 FS	*178.00 FS
4	1		*REAR BUMPER SPOILER	Cut	249.00 FS	*198.80 FS
5	1		*REAR BUMPER TRIM	Deformed	292.00 FS	*233.20 FS
6	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	232.00 FS	*- FS
7	2		*REAR TAIL LIGHT REFLECTOR - LH / RH	Not Necessary	82.00 FS	*- FS
8	1		*REAR TAIL LIGHT - LH	Not Necessary	1,019.00 FS	*- FS
9	1		*REAR TAIL LIGHT TRIM - LH	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	1,063.00 FS	*- FS
11	2		*REAR BUMPER SEAL	Not Necessary	28.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION - LH / RH	N/S Damaged	46.00 FS	*17.68 FS
13	2		*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	166.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
15	4		*REAR PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
16	1		*REAR LID	Dented	3,252.00 FS	*2,601.60 FS
17	1		*REAR LID GASKET	Not Necessary	205.00 FS	*- FS
18	1		*ADHESIVE	Necessary	19.00 FS	*14.88 FS
19	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
20	1		*A4 EMBLEM	Necessary	99.00 FS	*79.04 FS
21	1		*REAR LID LOCK	Not Necessary	230.00 FS	*- FS
22	1		*REAR LID COVER CAP	Not Necessary	8.00 FS	*- FS
23	1		*REAR LID PUSH BUTTON	Not Necessary	1,389.00 FS	*- FS
24	1		*REAR NO PLATE	Dented	60.00 FS	*60.00 FS
25	1		*SUNDRIES	Necessary	300.00 FS	*2.40 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	12,599.00 5,892.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,282.00	2,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >