

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0739/2021/ZK
DATE : 30-Sep-21
WIP : 43438

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 4/10/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHEANG SIEW KAY
ADDRESS : 39 JALAN SINAR BULAN

SINGAPORE 507051

TELEPHONE : HP +65 9738 0885
TYPE OF CLAIM : ~~THIRD PARTY CLAIM~~ *OD claim.*
POLICY NO : 1900133311-01
VEHICLE NO : SDD 3939 D
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 31/7/2019
ENGINE NO : CVK 081608
CHASSIS NO : WAUZZZF44KA071451
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Sep-21
PLACE OF ACCIDENT : TPE EXIT 2 SLIP ROAD / LOYANG AVENUE JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDD 3939 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT.	S/N \$	280.00	✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	2,450.00	1000
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	3,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 6,282.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 3939 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER COVER <i>Dehd</i>	1	\$ 2,996.00	✓
2	REAR BUMPER FIXING SET <i>neu</i>	1	\$ 459.00	+
3	REAR BUMPER SECURING STRIP <i>?</i>	1	\$ 223.00	?
4	REAR BUMPER SPOILER <i>lt</i>	1	\$ 249.00	✓
5	REAR BUMPER TRIM <i>Dehd</i>	1	\$ 292.00	✓
6	REAR BUMPER BRACKET - LH / RH <i>neu</i>	2	\$ 232.00	+
7	REAR TAIL LIGHT REFLECTOR - LH / RH <i>neu</i>	2	\$ 82.00	+
8	REAR TAIL LIGHT - LH <i>3 neu</i>	1	\$ 1,019.00	+
9	REAR TAIL LIGHT TRIM - LH <i>3 neu</i>	1	\$ 30.00	+
10	REAR BUMPER CARRIER <i>3 neu</i>	1	\$ 1,063.00	+
11	REAR BUMPER SEAL <i>3 neu</i>	2	\$ 28.00	+
12	REAR BUMPER GUIDE SECTION - LH / RH <i>3 neu</i>	2	\$ 46.00	+
13	REAR BUMPER HOLDING STRAP - LH / RH <i>3 neu</i>	2	\$ 166.00	+
14	REAR PARKING AID SENSOR <i>3 neu</i>	2	TBC	+
15	REAR PARKING AID SENSOR SEAL <i>3 neu</i>	4	\$ 14.00	+
16	REAR LID <i>Dented</i>	1	\$ 3,252.00	✓
17	REAR LID GASKET <i>neu neu neu</i>	1	\$ 205.00	+
18	ADHESIVE <i>3 neu</i>	1	\$ 19.00	✓
19	AUDI EMBLEM <i>3 neu</i>	1	\$ 138.00	✓
20	A4 EMBLEM <i>3 neu</i>	1	\$ 99.00	✓
SUB TOTAL SPARE PARTS			\$ 10,612.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 3939 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
20	REAR LID LOCK	1	\$ 230.00	+
21	REAR LID COVER CAP	1	\$ 8.00	+
22	REAR LID PUSH BUTTON	1	\$ 1,389.00	+
23	REAR NO PLATE	S/N	\$ 60.00	✓
24	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 12,369.00	
TOTAL LABOUR CHARGES		:	\$ 6,282.00	
GRAND TOTAL		:	\$ 18,651.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *04/10/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT