



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR XE5968P

SembWaste Pte Ltd

30 Hill Street
#05-04
Singapore 179360

67233200A/C

Vehicle & Document Information

WIP No 50926
Reg No/Reg Date XE5968P / 20/11/2020
Date In/Mileage XE5968P
Chassis No W1T964014204631007
Engine No 936912C0210734
Make/Model MBCV/Arocs 2630 6X4 3900
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WS000458	Credit	20/09/2021/ 12:12		610 / Philip Cheong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A. 00940101			35.00	468.00
TO REPLACE, REPAINT FRONT LEFT DAMAGE PARTS	1.00	839.88	30.00	587.92
M STEP PLATE	1.00	105.92	30.00	74.14
M ADD. TURN SIGNAL LAMP				

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

7% GST on 1130.06 1,130.06 79.10

Authorized signatory and company stamp

Total Payable 1,209.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714389
Fax: (65) 67756310
www.mercedes-benz.com.sg