

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SOH CHAN WAH
 12 DERBYSHIRE ROAD #04-01
 SINGAPORE 309466

Contact : 91790770

TR III
 Cecilia

ESTIMATE

Repair Code : CLM16951

Date in : 04/10/2021

Vehicle Num. : SKU7300Y

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11021183/L15B3521199

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	463.70	✓ 463.70
REAR BUMPER LOWER COVER <i>Dehd</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>LH could</i>	2	141.10	141.10 282.20
REAR BUMPER SIDE L/R <i>LH torn</i>	2	195.00	195 390.00
REAR BUMPER SIDE RETAINER L/R <i>could</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Dehd</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR <i>could</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>Dehd</i>	1	98.00	✓ 98.00
REAR FENDER ARCH GARNISH L/R <i>LH cracked</i>	2	195.00	195 390.00
REAR FENDER INNER TRIM GARNISH L/R <i>new</i>	2	295.00	+ 590.00
REAR FLOOR PANEL COMPARTMENT SPONGE TRAY <i>could</i>	1	485.30	285 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>torn</i>	1	430.30	285 430.30
REAR TAILGATE <i>Dented</i>	1	953.30	✓ 953.30
REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	✓ 56.20
REAR TAILGATE DAMPER L/R <i>new</i>	2	180.00	+ 360.00
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	+ 100.00
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	153.40	+ 153.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SOH CHAN WAH
 12 DERBYSHIRE ROAD #04-01
 SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM16951

Date in : 04/10/2021

Vehicle Num. : SKU7300Y

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11021183/L15B3521199

REAR TAILGATE INNER TRIM GARNISH <i>cancel</i>	1	180.00	✓ 180.00
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	✓ 180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>new</i>	1	27.50	+ 27.50
REAR TAILGATE OUTER GARNISH <i>new</i>	1	220.00	+ 220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>new</i>	1	25.00	+ 25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>new</i>	2	38.50	38.50 77.00
REAR TAILGATE REFLECTOR L/R <i>cancel</i>	2	413.20	413.20 826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	18.50	+ 37.00
REAR TAILGATE WEATHER STRIP <i>cancel</i>	1	96.80	✓ 96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>new</i>	2	50.00	40 100.00
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	2	50.00	40 100.00
REAR TAILLAMP L/R <i>cancel</i>	2	474.60	474.60 949.20
Subtotal before discount			8,428.20
Percentage discount 20%			1,685.64
Sub-total 1			6,742.56
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	280.00	200 280.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	20 60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM16951

Date in : 04/10/2021

Vehicle Num. : SKU7300Y

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11021183/L15B3521199

REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	+	60.00
REAR NUMBER PLATE <i>3 new</i>	1	25.00	+	25.00
REAR NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	60.00	30	60.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	+	40.00
REAR TAILGATE REVERSE CAMERA <i>new</i>	1	800.00	+	800.00
REAR TAILGATE SPOILER CLIPS - SET <i>new</i>	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	20	60.00
Subtotal before discount				1,595.00
Percentage discount 0%				0.00
Sub-total 2				1,595.00
Parts-total				8,337.56

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	100.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	800	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800	1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM16951

Date in : 04/10/2021

Vehicle Num. : SKU7300Y

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11021183/L15B3521199

To apply anti-rust chemical on repaired and replaced panel.

To remove n refix rear gate mechanism and check for function

2000

60 120.00

✓ 80.00

Labour Total

2,530.00

Parts & Labour Total

10,867.56

*** This is a computer-generated document which requires no signature.***

page 4

Adrian Lj

l/s 07/10/21

06 Days

total: 6353.84

l/s: SK ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: