

Vin's

Vin's Motor Pte Ltd
 140 Sun Ming Drive
 #03-03 Sun Ming Aulicity
 Singapore 519722
 Tel: 6453 2121 Fax: 6419 9795
 GST Registration No: 199906067G

Estimated Cost of Repair

Attention To : AXA Insurance Pte Ltd
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

Claim Details

Case Ref. No. : TP/102021/5016
 Date : 05-10-2021
 Accident Date : 03-10-2021

Vehicle Details

Make & Model : Toyota NOAH HYBRID 7-SEATER 1.8X CVT
 Chassis No : ZWR800502974
 Registration No : SNB2677H

Third Party Vehicle Details

Registration No : SHC3783T

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / <i>Acc</i>	1.00	\$1,672.70
2	REAR TAILGATE GLASS MOULDING @ \$67.50 / <i>acc</i>	2.00	\$135.00
3	REAR TAILGATE EMBLEM / <i>acc</i>	1.00	\$66.78
4	REAR TAILGATE "HYBRID" NAME PLATE / <i>acc</i>	1.00	\$49.80
5	REAR TAILGATE OUTER CHROME MOULDING / <i>acc</i>	1.00	\$909.80
6	REAR TAILGATE INNER TRIMBOARD / <i>acc</i>	1.00	\$673.00
7	REAR TAILGATE RUBBER / <i>Tri</i>	1.00	\$325.70
8	REAR TAILGATE INNER LOCK / <i>cut</i>	1.00	\$389.20
9	REAR TAILGATE PULL HANDLE COVER / <i>acc</i>	1.00	\$22.20
10	REAR RH CORNER PANEL X <i>NN</i>	1.00	\$229.80
11	REAR LH CORNER PANEL X <i>cut</i>	1.00	\$229.80
12	REAR BUMPER / <i>acc</i>	1.00	\$880.20
13	REAR BUMPER TOWING COVER X	1.00	\$29.90
14	REAR BUMPER RH REFLECTOR X	1.00	\$82.55
15	REAR BUMPER LH REFLECTOR X	1.00	\$82.55
16	REAR BUMPER RH SIDE RETAINER X	1.00	\$155.80
17	REAR BUMPER LH SIDE RETAINER X	1.00	\$155.80
18	REAR BUMPER CLIPS @ \$3.00 / <i>acc</i>	10.00	\$30.00
19	REAR END PANEL / <i>acc</i>	1.00	\$735.70
20	REAR END PANEL TOP TRIM / <i>acc</i>	1.00	\$282.10
21	REAR SPARE TYRE PANEL X <i>Hybrid</i>	1.00	\$781.70
22	REAR SPARE TYRE PANEL RH TOP COVER / <i>acc</i>	1.00	\$284.20
23	REAR SPARE TYRE PANEL LH TOP COVER / <i>acc</i>	1.00	\$284.20
24	REAR SPARE TYRE PANEL INSULATOR X <i>NN</i>	1.00	\$455.20
25	REAR CARGO COMPARTMENT BOX / <i>acc</i>	1.00	\$983.79
26	REAR RH FENDER INNER TRIMBOARD / <i>acc</i>	1.00	\$741.80
27	REAR LH FENDER INNER TRIMBOARD / <i>acc</i>	1.00	\$741.80
28	REAR FENDER INNER TRIMBOARD CLIPS @ \$3.00 / <i>acc</i>	10.00	\$30.00

\$11,441.07

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Discount -25% (\$2,860.31)

			\$8,580.76	
29	REAR TAILGATE REVERSE CAMERA - OM	1.00	\$380.00	250
30	REAR WINDSCREEN GUM - nbc	1.00	\$60.00	=
31	REAR NO. PLATE - Scr	1.00	\$40.00	=
32	REAR BUMPER PARKING SENSOR - OM	1.00	\$280.00	200
33	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00	120
34	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$280.00	X
35	TO REPAIR REAR DAMAGES	1.00	\$1,200.00	850
36	TO SPRAY PAINTING	1.00	\$1,200.00	950

Subtotal w/o GST: \$12,170.83

2x Tail lamp ~~##~~ - QA \$1,465.60

Keyless Sensor BR ✓ \$311.70

6 Days.
 # P/B
 before part photos.
 Eric Ong.
 06/10/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: