

# Vin's

Vin's Motor Pte Ltd  
140 Sun Ming Drive  
#03-03 Sun Ming Building  
Singapore 519722  
Tel: 6453 2121 Fax: 6454 9793  
GST Registration No: 199906067G

## Estimated Cost of Repair

Attention To : AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

### Claim Details

Case Ref. No. : TP/102021/5016  
Date : 05-10-2021  
Accident Date : 03-10-2021

### Vehicle Details

Make & Model : Toyota NOAH HYBRID 7-SEATER 1.8X CVT  
Chassis No : ZWR800502974  
Registration No : SNB2677H

### Third Party Vehicle Details

Registration No : SHC3783T

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / <i>Pnc</i>	1.00	\$1,672.70 ✓
2	REAR TAILGATE GLASS MOULDING @ \$67.50 / <i>acc</i>	2.00	\$135.00 ✓
3	REAR TAILGATE EMBLEM / <i>acc</i>	1.00	\$66.78 ✓
4	REAR TAILGATE "HYBRID" NAME PLATE / <i>acc</i>	1.00	\$49.80 ✓
5	REAR TAILGATE OUTER CHROME MOULDING / <i>acc</i>	1.00	\$909.80 581
6	REAR TAILGATE INNER TRIMBOARD / <i>acc</i>	1.00	\$673.00 570
7	REAR TAILGATE RUBBER / <i>Tri</i>	1.00	\$325.70 ✓
8	REAR TAILGATE INNER LOCK / <i>cut</i>	1.00	\$389.20 ✓
9	REAR TAILGATE PULL HANDLE COVER / <i>acc</i>	1.00	\$22.20 ✓
10	REAR RH CORNER PANEL X <i>NN</i>	1.00	\$229.80
11	REAR LH CORNER PANEL X <i>cut</i>	1.00	\$229.80
12	REAR BUMPER / <i>acc</i>	1.00	\$880.20 822.3
13	REAR BUMPER TOWING COVER X	1.00	\$29.90
14	REAR BUMPER RH REFLECTOR X	1.00	\$82.55
15	REAR BUMPER LH REFLECTOR X	1.00	\$82.55
16	REAR BUMPER RH SIDE RETAINER X	1.00	\$155.80
17	REAR BUMPER LH SIDE RETAINER X	1.00	\$155.80
18	REAR BUMPER CLIPS @ \$3.00 / <i>acc</i>	10.00	\$30.00 ✓
19	REAR END PANEL / <i>Pnc</i>	1.00	\$735.70 691
20	REAR END PANEL TOP TRIM / <i>acc</i>	1.00	\$282.10 204.5
21	REAR SPARE TYRE PANEL X <i>Hybrid</i>	1.00	\$781.70
22	REAR SPARE TYRE PANEL RH TOP COVER / <i>acc</i>	1.00	\$284.20 198
23	REAR SPARE TYRE PANEL LH TOP COVER / <i>acc</i>	1.00	\$284.20 198
24	REAR SPARE TYRE PANEL INSULATOR X <i>NN</i>	1.00	\$455.20
25	REAR CARGO COMPARTMENT BOX / <i>acc</i>	1.00	\$983.79 845
26	REAR RH FENDER INNER TRIMBOARD / <i>acc</i>	1.00	\$741.80 612
27	REAR LH FENDER INNER TRIMBOARD / <i>acc</i>	1.00	\$741.80 612
28	REAR FENDER INNER TRIMBOARD CLIPS @ \$3.00 / <i>acc</i>	10.00	\$30.00 ✓

\$11,441.07 8055.18

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

Discount -25% (\$2,860.31)

29	REAR TAILGATE REVERSE CAMERA	1.00	\$8,580.76	6041.38
30	REAR WINDSCREEN GUM	1.00	\$380.00	250
31	REAR NO. PLATE	1.00	\$60.00	=
32	REAR BUMPER PARKING SENSOR	1.00	\$40.00	=
33	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$280.00	200
34	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$150.00	120
35	TO REPAIR REAR DAMAGES	1.00	\$280.00	X
36	TO SPRAY PAINTING	1.00	\$1,200.00	850
		1.00	\$1,200.00	850

Subtotal w/o GST: \$12,170.83 2500

2x Taillamp ~~1465.6~~ / 1465.6

KEYLESS SENSOR ✓ BR 311.7

6 Days.

1/8

before photos.

Eno Conf.

06/10/21

9874.36

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.