

5<sup>th</sup> Oct 2021

Quotation No.: Q21-OPS-1390

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way AIG Building #07-16  
Singapore 079120  
By Fax : 68357416

Dear Sir/Mdm

**Estimated Cost of Repair job for SBS6455H (Accident on 29/09/2021 @ Lor Chuan & Ang Mo Kio Ave 1 involving SBS6455H & SML5760P)**

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled painter & paint material to Putty, grinding & spraypaint - rear RHS wheelarc panel - rear RHS bodypanel	2 day	\$880.00	\$1,760.00 ✓
2	RHS indicator lamp	1 PC	\$111.45	\$111.45 ✓ c/a
3	RHS marker lamp	1 PC	\$145.20	\$145.20 X Svc
4	Screw	2 PC	\$3.15	\$6.30 X Svc
5	SG<3Bus Sticker	1 PC	\$150.00	\$150.00 ✓ nec
Sub Total				\$2,172.95

**Terms and Conditions:**

Payment Terms : 30 days upon invoice  
Quotation Validity : 30 days  
Lead-Time : 2 working day  
Price quoted subject to 7% GST

Yours faithfully

*Tien yong shun*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Thuan @ Lkh auto . com  
8223 5769  
6/10/21 1200

PIP after bfr paint photo  
w p 3clays  
F: \$1495.31

**LexBuild International Pte. Ltd.**

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.  
Tel (65) 6456 3533, Fax: (65) 6456 3353  
Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R