

SEA FILE BY: Thuan

REF:

CC4/AIG 21010285/Pa3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SBS 6455H ✓

Yr Regn: _____

117/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mercedes Benz Citaro c.c. 6374

Colour: _____

green

A/C: Insured / Std / NI / NA

Sp. Reading: _____

1903.164

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WE B62808323/25401

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIRIm / STD A/RIm or

Tyre Size: F: _____

R: _____

275/70 R22.5

275/70 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 29/9/21

D.O.I. 6/10/21

1200

Survey held at

Go ahead depot longang

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

rebate: 0

Date/Time. File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: W/ser end

Survey Fee:

Transportation:

S + RS. \$

Pinus

Calves

Total

Report Form 1:

Long Sing / LE: 12

5th Oct 2021

Quotation No.: Q21-OPS-1390

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way AIG Building #07-16
Singapore 079120
By Fax : 68357416

Dear Sir/Mdm

Estimated Cost of Repair job for SBS6455H (Accident on 29/09/2021 @ Lor Chuan & Ang Mo Kio Ave 1 involving SBS6455H & SML5760P)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled painter & paint material to Putty, grinding & spraypaint - rear RHS wheelarc panel - rear RHS bodypanel	2 day	\$880.00	\$1,760.00 ✓
2	RHS indicator lamp	1 PC	\$111.45	\$111.45 ✓ CIA
3	RHS marker lamp	1 PC	\$145.20	\$145.20 X SVC
4	Screw	2 PC	\$3.15	\$6.30 X SVC
5	SG<3Bus Sticker	1 PC	\$150.00	\$150.00 ✓ nec
Sub Total				\$2,172.95

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 2 working day
Price quoted subject to 7% GST

Yours faithfully

Tien yong shun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Thuan@Lkh auto . com
8223 5769
6/10/21 1200

Plp after ffpaint photo
w p 3clays

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	900C
Vehicle Details	
Vehicle No.:	SBS6455H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530 6.4L AT TURBO ABS
Primary Colour:	Multicolor
Manufacturing Year:	2013
Engine No.:	902926C1032404
Chassis No.:	WEB62808323125401
Maximum Power Output:	-
Open Market Value:	\$312,919.00
Original Registration Date:	01 Jul 2014
First Registration Date:	01 Jul 2014
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 12 Oct 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/10/2021 12:03 (SGT)
Date of Accident	29/09/2021 20:20 (SGT)
Exact Location of Accident	Lor Chuan & Ang Mo Kio Ave 1, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS6455H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Go Ahead Singapore Pte Ltd
Company Reg No	2XXXXX900C
Email Address	claimsmatter@go-aheadsingapore.com
Mobile Phone No	(Phone) +65-63847169
Alternative Phone No	(Office) +65-63847169

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Citro
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	6400

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	D-19094111MFB
Cover Note Number	-

DRIVER

Name of Driver	Zulkiflee Bin Lebar
Work Permit No	GXXXX432L

Date Of Birth	18/10/1970
Occupation	Outdoor
Date Of Driving Pass	24/05/2018
Driving experience	3 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86159274
Alt. Phone Number	-
Email Address	claimsmatter@go-aheadsingapore.com
Address	2 LOYANG WAY
Address complement	-
Postcode	508776
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

BC Zulkiflee was driving service 136 [SBS6455H] on the above-mentioned date & time. Whilst heading towards the above-mentioned location via the extreme left lane of a 3-lane road along Lor Chuan when a black Mazda 2 [SML5760P] travelling on the adjacent lane veered towards SBS6455H where SML5760P's front left fender & mirror were damaged after side sweeping against SBS6455H's rear right signal light cover & body panel

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	DIFFERENT FORMAT
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML5760P
Vehicle Manufacturer	Mazda
Vehicle Model	2
Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	Goh Jianyi, Stephanie

NRIC No	SXXXX132Z
Contact Number	-
Address	550A Segar Rd
Address complement	#06-618
Postcode	671550
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

