

Hiap Hong Motor Repair

2, Kaki Bukit Avenue 2, #02-13, Kaki Bukit AutoHub, Singapore 417921
Tel: 6745 9633 Fax: 6747 8602 Email: hiap.hong.motor@gmail.com
Company Reg. No.: 42051700-J

31 December 2019

FINAL REPAIR BILL

M/s. Richland Logistics Services Pte Ltd
11 Bedok North Ave 4 #05-01
Richland Business Centre
Singapore 489949

Dear Sirs,

RE: FINAL REPAIR BILL TO MOTOR VEHICLE NO. YP7148G

We refer to the above mentioned vehicle. The cost of repair and replacement parts of the said vehicle have been adjusted to a lump sum amount totalling:
S\$ 7,100.00

Dollars: Seven Thousand And One Hundred Only

Yours faithfully


.....
Chua Meng Liang