

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

Xiao Chen.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0811/2021/KS

18-Oct-21

CHANG

1 of 1

SMX 4006 C

AUDI A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	HEADLIGHT COVER - LH <i>inbed</i>	\$ 44.00	<i>✓</i> 34.48
2	HEADLIGHT WASHER BRACKET - LH <i>inbed</i>	\$ 15.00	<i>✓</i> 11.76
GRAND TOTAL		\$ 59.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
18/10/21
[Signature]

Car-in

14/10/21

wip: 47535


PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

kiam/



AIG-Adrian

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>chd</i>	1	S 2,342.00	✓
2	FRONT BUMPER SECURING STRIP <i>neu</i>	2	S 71.00	+
* (3)	FRONT BUMPER GRILLE <i>neu</i>	1	S 196.00	+
(4)	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>chd</i>	1	S 262.00	✓
5	FRONT BUMPER AIR GUIDE - LH <i>neu</i>	1	S 63.00	+
(6)	FRONT BUMPER CLOSING ELEMENT <i>chd</i>	1	S 262.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	1	S 135.00	+
8	FRONT BUMPER LOWER TRIM - LH <i>neu</i>	1	S 48.00	+
9	FRONT BUMPER LOWER TRIM - CENTER <i>neu</i>	1	S 114.00	+
10	RADIATOR GRILLE <i>chd</i>	1	S 1,694.00	✓
(11)	FOAM FILLER PIECE <i>chd</i>	1	S 146.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM	1	S 845.00	?
13	FRONT BUMPER GUIDE SECTION - LH <i>neu</i>	1	S 36.00	+
14	FRONT BUMPER TOP COVER <i>neu</i>	1	S 127.00	+
15	"CAUTION" STICKER <i>neu</i>	1	S 14.00	+
16	"A/C" STICKER	1	S 8.00	+
(17)	LOCK CARRIER TOP BRACKET <i>chd</i>	1	S 137.00	✓
18	LOCK CARRIER SUPPORT BRACKET - LH / RH <i>neu</i>	2	S 58.00	+
19	FRONT PARKING AID SENSOR - FRONT OUTER	1	TBC	+
20	FRONT PARKING AID SENSOR - FRONT INNER	1	TBC	+
TOTAL SPARE PARTS		:	\$ 6,558.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

N 016 185 7 X 6

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SEAL RING	4	\$ 14.00	+
22	HORN - LH	1	\$ 126.00	+
23	HORN BRACKET - LH	1	\$ 29.00	+
24	BONNET <i>Dented</i>	1	\$ 3,312.00	✓
25	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 123.00	+
26	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$ 28.00	+
27	BONNET IMPACT PROTECTION - LH / RH	2	\$ 56.00	✓
28	BONNET STRIKER - LH	1	\$ 50.00	+
29	BONNET LID LOCK	1	\$ 214.00	+
30	BONNET LOCK COVER	1	\$ 44.00	+
31	FRONT FENDER - LH <i>Backend</i>	1	\$ 1,060.00	✓
32	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 53.00	+
33	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 74.00	+
34	FRONT FENDER BRACKET - LH	1	\$ 35.00	?
35	FRONT FENDER BRACE - LH	1	\$ 118.00	?
36	FRONT FENDER FLEDGE COVER - LH LONG <i>new</i>	1	\$ 36.00	+
37	FRONT FENDER FLEDGE COVER - LH SHORT	1	\$ 16.00	+
38	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 275.00	+
39	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>new</i>	1	\$ 169.00	+
40	FRONT WHEEL SPOILER - LH <i>new torn</i>	1	\$ 73.00	✓
SUB TOTAL SPARE PARTS			\$ 5,905.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH <i>new</i>	1	\$ 164.00	✓
(42)	LED HEADLIGHT - LH <i>cracked</i>	1	\$ 7,685.00	✓
43	LIFT CYLINDER - LH <i>new</i>	1	\$ 198.00	✗
44	LIFT CYLINDER HOSE - LH	1	TBC	✗
45	RADIATOR AIR GUIDE - LH	1	\$ 31.00	✗
46	RADIATOR AIR GUIDE - LH	1	\$ 16.00	✗
47	RADIATOR AIR GUIDE - UPPER	1	\$ 16.00	✗
48	FRONT DOOR CHROME TRIM - LH	1	\$ 164.00	✗
49	FRONT NO PLATE <i>Dented</i>	1	\$ 60.00	✓
50	SUNDRIES	1	\$ 300.00	✓
TOTAL SPARE PARTS		:	\$ 21,097.00	
TOTAL LABOUR CHARGES		:	\$ 8,552.00	
GRAND TOTAL		:	\$ 29,649.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.