

TP AXA.
Hui Zhen.

SKF4985U 2012 June

Honda Odyssey 2354CC

JHMRB3850CC200445

Rear Bumper ~~Defend~~ 783 ✓

Rear Bumper Clips. ~~new~~ 30(SN) ✓

Rear Bumper Side Holder LH. ~~new~~ 24.50 X

Rear Bumper Lower Spoiler ~~R/L~~ 523. X

Rear LH Wheel Rim. ~~new~~ 750(SN) X

783 S.N. 30

616-40

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel Beating ~~400~~ 300

Spray Painting ~~800~~ 400

To remove reverse sensor 50 ✓ 730.

To perform wheel alignment. 150. X.

TOTAL \$2744.40

total: 138640

2/c: 1.1K. ✓
03 Days.