



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Invoice

Customer: STS Transport Management Pte Ltd
C/o: 15, Pioneer Sector 2
Singapore 628376

Date: 19.07.2021

Invoice No: NS-2021-106

Description		Amount
Vehicle No:	PC1655Z	
Make & Model:	Golden Dragon XML6957J14 (Bus)	
Our reference:	AAS/2021/106	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Two hundred seventy six dollar only	Total:	SGD \$ 276.00

Notes:


All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: STS Transport Management Pte Ltd
C/o: 15, Pioneer Sector 2
Singapore 628376

Date of report: 19.07.2021
Date of request: 28.04.2021
Date of inspection: 28.04.2021
Date of accident: 01.04.2021
Claim type: Third Party Claim

Report No: AAS/2021/106

Particulars of affected vehicle:

Registration no:	PC1655Z	Odometer:	452057 km
Make/Model:	Golden Dragon XML6957J14 (Bus)	Engine Capacity:	6693 cc
Year of registration:	2011/12	Engine no:	ISBE422521980349
Colour:	Multi-Colour	Chassis no:	LL3BECDH3BA013097

Condition of tires:

Front Left:	12mm	Front Right:	12mm
Make:	Westlake	Make:	Westlake
Rear Left:	12mm	Rear Right:	12mm
Make:	Westlake	Make:	Westlake

Type of road wheel: STD (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conduct at M/s. STS Transport Management Pte Ltd
15, Pioneer Sector 2
Singapore 628376

Assessment

Repairer's estimate:	\$ 900.00
Revised estimate:	\$ 600.00
Recommended reserve:	\$ 600.00 (Part by Part)

Estimated normal duration of repairs : 2 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: PC1655Z

Report No: AAS/2021/106

W/O PREJUDICE

Point of impact

At the RHR portion.

General description of damages

The rear panel and RHR corner panel.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s STS Transport Management Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$600.00

Conclusion

The repairer has agreed to undertake the repair on a Part by Part basics of SGD \$600.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 2 working days.


We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 16 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: PC1655Z

Report No: AAS/2021/106

Appraisement Schedule

S/N Parts Description	Qty	Condition	Repairer's Est	Revised Est
1 Rear panel		Dented/Repair	-	-
2 RHR quarter panel		Grazed/Repair	-	-
Total:			\$ -	\$ -
-10%			\$ -	\$ -
List total:			\$ -	\$ -

S/N Labour Description	Repairer's Est	Revised Est
1 Panel beat, reform, repair rear panel & RHR quarter.	\$ 300.00 150	\$ 200.00
2 To putty, grind smoothen & respray affected panels.	\$ 600.00 350	\$ 400.00
Labour Total:	\$ 900.00	\$ 600.00
Grand Total:	\$ 900.00	\$ 600.00

The final adjusted Part by Part amount is \$600.00

Under normal circumstances, the repair should be completed within a reasonable period of 2 working days.

16 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

