

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@rico60.com

Tel: 6286 6060 Fax : 6286 7060

vFIRFA00260211851

RICO Office Use Only

Parts -10%	
SN	
Labour	
Total	
Lump Sum	
ERV	44K

LKK

TO: CT
Vehicle No : SMH 3356 H
Make & Model : RENAULT SCENIC
DATE: 5/10/2021

o.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	TAILGATE <i>Regis</i>	1	\$ 5,854.00	\$ 5,854.00	+
2	TAILGATE OUTER COVER <i>Regis</i>	1	\$ 1,512.00	\$ 1,512.00	+
3	TAILGATE WINDSCREEN WITH MOULDING <i>Not m</i>	1	\$ 1,845.00	\$ 1,845.00	+
4	TAILGATE EMBLEM(SCENIC) <i>New</i>	1	\$ 122.00	\$ 122.00	+
5	TAILGATE OUTER CHROME <i>New</i>	1	\$ 485.00	\$ 485.00	+
6	REVERSE CAMERA <i>New</i>	1	\$ 1,542.00	\$ 1,542.00	+
7	TAILGATE NUMBER PLATE LAMP <i>New</i>	2	\$ 154.00	\$ 308.00	+
8	TAILGATE OPENER SWICTH <i>New</i>	1	\$ 217.90	\$ 217.90	+
9	TAILGATE STOPPER <i>New</i>	2	\$ 25.00	\$ 50.00	+
0	TAILGATE INNER LOCK <i>Not m</i>	1	\$ 685.00	\$ 685.00	+
1	TAILGATE LOCK CATCH <i>New</i>	1	\$ 46.00	\$ 46.00	+
2	TAILGATE WEATHERSTRIP <i>Not m</i>	1	\$ 385.00	\$ 385.00	+
3	TAILGATE LOCK DETECTOR <i>crackd</i>	1	\$ 452.00	\$ 452.00	155
4	TAIL LAMP <i>New</i>	2	\$ 685.00	\$ 1,370.00	+
5	TAIL LAMP BOTTOM RETAINER <i>New</i>	2	\$ 158.00	\$ 316.00	+
6	REAR BUMPER <i>Del d</i>	1	\$ 2,145.00	\$ 2,145.00	152
7	REAR BUMPER SIDE RETAINER <i>New crackd</i>	2	\$ 168.00	\$ 336.00	+
8	REAR BUMPER CENTER RETAINER <i>crackd</i>	1	\$ 217.30	\$ 217.30	+
9	REAR BUMPER REINFORCEMENT <i>New</i>	1	\$ 874.00	\$ 874.00	+
0	RAER BUMPER DIFFUSER <i>Del d</i>	1	\$ 698.00	\$ 698.00	320
1	REAR BUMPER REFLECTOR <i>crackd</i>	2	\$ 354.00	\$ 708.00	420
2	REAR BUMPER SIDE BOTTOM BRACKET <i>New</i>	2	\$ 154.00	\$ 308.00	+
3	REVERSE SENSOR <i>2 Pieces damaged</i>	4	\$ 394.00	\$ 1,576.00	490
4	REVERSE SENSOR WIRING <i>New</i>	1	\$ 685.00	\$ 685.00	+
5	END PANEL <i>New</i>	1	\$ 1,245.00	\$ 1,245.00	+
6	END PANEL TOP TRIM <i>Not New</i>	1	\$ 288.70	\$ 288.70	+

27	REAR FLOOR PANEL	1	\$	896.50	\$	896.50	+
28	REAR FLOOR PANEL TOP BOARD	1	\$	842.00	\$	842.00	+
29	REAR FLOOR CENTER BOARD	1	\$	546.00	\$	546.00	+
30	REAR FLOOR PANEL TOOL SPONGE	1	\$	355.00	\$	355.00	+
31	REAR FENDER INNER TRIM	2	\$	657.00	\$	1,314.00	+
32	REAR FENDER INNER SHIELD	2	\$	198.70	\$	397.40	+
33	REAR FENDER AIR VENT	2	\$	85.00	\$	170.00	+
34	REAR EXHAUST SILENSER	1	\$	1,019.00	\$	1,019.00	+
35	REAR EXHAUST MOUNTING	2	\$	50.00	\$	100.00	+
36	REAR EXHAUST HEAT PLATE	1	\$	415.00	\$	415.00	+

325230

2927.07

Subtotal : \$ 30,325.80

Less 10% \$ 3,032.58

Parts Total : \$ 27,293.22

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR WINDSCREEN SEALANT <i>not ne</i>	1	\$ 80.00	\$ 80.00	42+
2	REAR WINDSCREEN INNER SEAL <i>not ne</i>	1	\$ 60.00	\$ 60.00	40+
3	TAILGATE OUTER COVER CLIPS <i>Ne</i>	1	\$ 120.00	\$ 120.00	30.
4	REAR BUMPER CLIP <i>Ne</i>	1	\$ 50.00	\$ 50.00	✓
5	REAR BUMPER UNDER COVER CLIP <i>Ne</i>	1	\$ 40.00	\$ 40.00	+
6	END PANEL SEALANT <i>Ne</i>	1	\$ 80.00	\$ 80.00	+
7	END PANEL TOP TRIM CLIP <i>Ne</i>	1	\$ 30.00	\$ 30.00	10.
8	REAR FLOOR PANEL SEALANT	1	\$ 150.00	\$ 150.00	+
9	REAR FENDER INNER TRIM CLIP	1	\$ 50.00	\$ 50.00	+
10	REAR FENDER INNER TOP TRIM CLIP <i>not ne</i>	1	\$ 50.00	\$ 50.00	+
11	REAR FENDER INNER SHIELD CLIP	1	\$ 50.00	\$ 50.00	+
				\$ 760.00	

90

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00 400
TO SPRAY PAINT AFFECTED AREA	\$ 1,500.00 500
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00 30.
TO APPLY ANTI-RUST & TUFF KOTE	\$ 150.00 x.
REMOVE AND INSTALL REAR WINDSCREEN	\$ 150.00 X
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART	\$ 150.00 X
REMOVE INSTALL AND CHECK REVERSE CAMARA	\$ 200.00 50
REMOVE INSTALL AND CHECK REVERSE SENSOR	\$ 200.00 50.
REMOVE AND INSTALL CARPET, TRIM AND INTERRIOR	\$ 400.00 x.
REMOVE AND INSTALL REAR EXHAUST	\$ 150.00 x
1630	
LABOUR TOTAL	\$ 4,650.00

	Total Parts Cost	\$ 28,053.22
	Total Labour Cost	\$ 4,650.00
	Total Repair Cost	\$ 32,703.22

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King

H/S 06/10/21.

04 Days.

total: 4047.07

H/S: 3.2k ✓