

ASS. REC. BY:

Steve

CS/CT121010297/Egy3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

SNM21D205536/C01

Sum Insured:

Excess:


6000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Sent

Consistent? : Yes or No

Est. Repairs:

21 days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date:

Person Contacted:

Veh No:

SJE17H

Yr Regn:

8/8/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche 911 Carrera

cc 2981

Colour:

Grey

A/C: Insured / Std / NI / N

Sp. Reading

N/A

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

WPO222 942LS215500

Gen. Condi: Good / Fair / Poor / Bunt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245 / 35 ZR 20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/9/21

D.O.A.

6/10/21

Survey held at

Stuttgart

Arb

Des. of Damages

Frnt

Rear

O/S

N/S

U/C

Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-560K

06/10/21 @ 4.35pm revert to Alfred Toh via Merimen. (PENDING FOR SITE INSPECTION)

21/10/21 @ 3.07pm 2nd IA revert to Alfred Toh via Merimen.

22/10/21 @ 4.33pm Albert Chua informed C/A via Merimen

25/10/21 @ 9.38am Informed Jobi C/A & ex: \$6000 by email.

28/03/22 @ 2.45pm confirmed with Jobi final fig. \$137915.43, 21 days. (Red \$32388.20, 19%)

Time/Time, File, Return to:



Procl. Report

Days Of Repair:

21

28/03 Typist



Final Report

Resurvey No. of Trips:

5

Survey Fee:

Transportation

Time/Time, File, Return to:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

VVest/Incl (\$

Site ins

150/-

150/-

150/-

Time/Time, File, Return to:

MER-OD

Time/Time, File, Return to:

137915.43



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042 EUROKARS GROUP
ESTIMATE COST OF REPAIRS

PORSCHE

CHINA TAIPING INSURANCE (SINGAPORE)		NAME :		WIP :		22480	
3 Anson Road		ADDRESS :		EXCESS :			
#16-00 Springleaf Tower				DATE:		5-Oct-21	
Singapore 079909		TEL :					
ATTN. : MOTOR CLAIMS							
FAX :							
VEH NO :	SJE17H	DATE IN :		CONTACT PERSON :		JOB#	63310682
CHASSIS NO :	WP0ZZZ99ZLS215500	MILEAGE :		TYPE OF CLAIM :		OWN DAMAGE	
MODEL :	911 Carrera 4S	DATE REG.:	8-Aug-19	POLICY NO. :			
NATURE OF WORKS							
S/NO	Parts Description			QTY	1ST	SUPP	REVISED
							PRICES
1	FRONT FENDER LH	✓	00	1			\$ 1,327.60
2	FRONT FENDER RH	✓	00	1			\$ 1,327.60
3	RAIL WING LH	?		1			\$ 55.70
4	RAIL WING RH	?		1			\$ 55.70
5	FENDER STRUT BRACE LH& RH	✓	MIS	2			\$ 70.20
6	FENDER RADIUS ROD BRACE	✓	MIS	2			\$ 72.40
7	WHEEL HOUSING LINER FRONT LH	✓	OR	1			\$ 303.90
8	WHEEL HOUSING LINER FRONT RH	✓	MIS	1			\$ 303.90
9	WHEEL HOUSING LINER FRONT REAR LH	?		1			\$ 339.30
10	WHEEL HOUSING LINER FRONT REAR RH	?		1			\$ 339.30
11	FRONT BUMPER	✓	OR	1			\$ 2,280.80
12	FRONT BUMPER LOWER SPOILER	✓	MIS	1			\$ 444.40
13	TRIM FOR AIR INLET CENTER	✓	OR	1			\$ 265.50
14	BRACKET FOR ULTRASOUND SENSOR LH	✓	NCC	1			\$ 50.90
15	BRACKET FOR ULTRASOUND SENSOR RH	✓	NCC	1			\$ 50.90
16	SENSOR OUTER	✓	MIS	2			\$ 503.80
17	SENSOR INNER	✓	shorted	2			\$ 503.80
18	SENSOR GASKET	✓	NCC	1			\$ 3.10
19	GRILLE CENTER CLOSE	✓	MIS	1			\$ 268.50
20	BRACKET GRILLE CENTER	✓	MIS	1			\$ 205.20
21	GRILLE LH	✓	OR	1			\$ 227.50
22	GRILLE RH	✓	OR	1			\$ 227.50
23	GRILLE FLAP LH	✓	OR	1			\$ 570.10
24	GRILLE FLAP RH	✓	OR	1			\$ 570.10
25	EXTERNAL TEMPERATURE SENSOR	✓	MIS	1			\$ 65.00
26	LENS-HEAD SCREW	✓	NCC	10			\$ 20.00
27	POP RIVET	✓	NCC	4			\$ 6.00
28	NUMBER PLATE BRACKET	✓	MIS	1			\$ 78.40
29	FRONT BUMPER REINFORCEMENT	✓	00	1			\$ 1,516.30
30	FRONT BUMPER LOWER REINFORCEMENT	✓	MIS	1			\$ 502.80
31	REINFORCEMENT GASKET	✓	NCC	2			\$ 66.00
32	RIVETTED CAP NUT	✓	NCC	8			\$ 10.40
33	BONNET	✓	00	1			\$ 3,092.90
34	HINGE LH	?		1			\$ 152.00

35	HINGE RH	1	P992-823-296- Y-GRV		\$	152.00
36	CONSOLE FOR HINGE LH	1	P992-823-611- Y-		\$	53.20
37	CONSOLE FOR HINGE RH	1	P992-823-612- Y-		\$	53.20
38	BONNET DAMPER	2	P992-823-359- -		\$	141.80
39	LOCK UPPER PART	1	P991-823-085- -		\$	36.80
40	PORSCHE CREST	1	P991-853-601- -		\$	262.50
41	DESK PAD CREST	1	P991-853-611- -		\$	16.80
42	SEAL FOR BONNET	1	P992-823-727-A -		\$	205.00
43	HINGE COVER LH	1	P992-823-745- -		\$	47.90
44	HINGE COVER RH	1	P992-823-746- -		\$	47.90
45	RUBBER BUFFER	2	P991-823-499- -		\$	12.60
46	HEXAGON NUT	4	PN -911-893-03-		\$	10.80
47	BONNET LOCK	1	P992-823-509-M -		\$	596.60
48	HORN HIGH TONE	1	P992-951-212-A -		\$	182.40
49	HORN LOW TONE	1	P992-951-211-A -		\$	182.40
50	BRACKET FOR HORN	1	P992-907-333- -		\$	71.30
51	HORN FRO ALRM SYSTEM	1	P971-951-101- -		\$	66.30
52	BRACKET FOR HORN ALARM	1	P992-951-227- -		\$	54.30
53	TURN SIGNAL REPEATER LH	1	P992-953-041-C -		\$	150.10
54	TURN SIGNAL REPEATER RH	1	P992-953-042-C -		\$	150.10
55	FRONT LIGHTS LH	1	P992-941-311-A -		\$	871.30
56	FRONT LIGHTS RH	1	P992-941-312-A -		\$	871.30
57	LED HEADLIGHT LH	1	P992-941-043-H -		\$	5,714.00
58	LED HEADLIGHT RH	1	P992-941-044-H -		\$	5,714.00
59	SEAL LH	1	P992-941-119-C -		\$	110.50
60	SEAL RH	1	P992-941-120-C -		\$	110.50
61	END CAP WITH SEAL LH	1	P992-941-809- -		\$	44.00
62	END CAP WITH SEAL RH	1	P992-941-810- -		\$	44.00
63	RETAINING FRAME FOR HEADLIGHT LH	1	P992-941-046- -		\$	44.00
64	RETAINING FRAME FOR HEADLIGHT RH	1	P992-941-046-A -		\$	44.00
65	FAN FOR HEADLAMPS	2	P992-903-171- -		\$	334.60
66	VENTILATION COMPONENT	2	P991-941-730- -		\$	97.80
67	LED MODULE	2	P992-919-172-A -		\$	836.40
68	CONTROL UNIT FOR LED HEADLIGHT	2	P992-941-572-BB-		\$	1,254.00
69	FRONT LOCK TOP COVER	1	P992-863-475-A -OK1		\$	221.10
70	SPACER PIECE	10	P9A7-007-207-00-		\$	29.00
71	TOP COVER RH	1	P992-821-942-C-OK1		\$	131.70
72	WIRING SET FOR FRONT BUMPER LH	1	P992-972-155-C -		\$	538.50
73	WIRING SET FOR FRONT BUMPER RH	1	P992-972-156-A -		\$	269.30
74	WIRING HARNESS SECTION FOR LIGHTNING LH	1	P992-970-248- Y-		\$	1,852.70
75	WIRING HARNESS SECTION FOR LIGHTNING RH	1	P992-970-242- Y-		\$	1,482.10
76	REFRIGERANT LINE	1	P992-816-528-C -		\$	349.10
77	REFRIGERANT LINE TO CONDENSER	1	P992-816-530- -		\$	429.30
78	BRACKET FOR REFRIGERANT PIPE	1	P992-820-761-A -		\$	22.10
79	SUPPORT BRACKET FOR PIPE	2	P971-260-197- -		\$	29.40
80	BRACKET FOR REFRIGERANT PIPE	1	P991-816-765- -		\$	22.00
81	COMBINATION HOLDER	1	PPAF-108-488- -		\$	12.20
82	A/C CONDENSER LH & RH	2	P992-820-411- -		\$	1,459.40
83	SEALING FRAME	2	P992-820-860- -		\$	176.60
84	AIR GUIDE CENTER	1	P992-815-217- -OK1		\$	245.10
85	AIR GUIDE LH	1	P992-815-215- -OK1		\$	221.70

86	AIR GUIDE RH	1	P992-815-216- -OK1		\$	221.70
87	P9A7-820-535- -/EXTERNAL TEMPERATURE SENSOR	1	P820-820-535-A -		\$	58.50
88	RADIATOR LH	1	P992-121-251- -		\$	1,825.00
89	RADIATOR RH	1	P992-121-252- -		\$	1,825.00
90	RADIATOR FAN	2	P992-959-447-A -		\$	2,680.60
91	CARRIER RADIATOR FAN	2	P992-121-435- -		\$	241.20
92	FAN HOUSING LH	1	P992-121-383-A -		\$	536.10
93	FAN HOUSING RH	1	P992-121-384-A -		\$	536.10
94	AIR GUIDE REAR LH	1	P992-121-333- -		\$	234.60
95	AIR GUIDE REAR RH	1	P992-121-334- -		\$	234.60
96	SPREADER RIVET	8	P5K0-837-975-A -		\$	230.40
97	COOLANT HOSE LONG LH	1	P992-121-623-B -		\$	1,005.20
98	COOLANT HOSE LONG RH	1	P992-121-624-B -		\$	1,005.20
99	COOLANT HOSE SHORT LH	1	P992-121-611-A -		\$	1,005.20
100	COOLANT HOSE SHORT RH	1	P992-121-612-A -		\$	1,005.20
101	BREATHING LINE LH	1	P992-121-465- -		\$	95.10
102	BREATHING LINE RH	1	P992-121-466- -		\$	95.10
103	SEAL	4	P992-121-228-A -		\$	106.80
104	SEAL	2	P992-121-228-B -		\$	36.80
105	P000-043-301-12-/ANTIFREEZE PROTECTION	6	P000-043-305-15-		\$	211.20
106	FRONT WINDSCREEN	1	P992-845-011-AQ-		\$	2,307.40
107	STEERING AIRBAG	1	P992-880-201-B -TST		\$	2,622.30
108	PASSENGER AIRBAG	1	P992-880-204-B -		\$	2,280.20
109	HEAD AIRBAG UNIT LH	1	P992-880-741-D -		\$	1,596.10
110	HEAD AIRBAG UNIT RH	1	P992-880-742-D -		\$	1,596.10
111	CONTROL UNIT FOR AIRBAG	1	P992-959-655-B -		\$	2,137.00
112	CRASH SENSOR FOR AIRBAG	2	P992-959-651- -		\$	684.00
113	DASHBOARD SLATE GREY	1	P992-857-003-N -OU6		\$	5,819.10
114	ROOF LINING	1	P992-867-501-AL-OU6		\$	2,850.30
115	COVER FRAME SEAL	1	P992-867-561-A -		\$	290.70
116	FRONT SEATBELT LH & RH	2	P992-857-705-M -OX6		\$	2,052.20
117	SEATBELT BUCKLE LH	1	P992-857-755-B -		\$	273.60
118	SEATBELT BUCKLE RH	1	P992-857-756-B -		\$	273.60
119	CROSS PANEL BOOT PLATE FRONT	1	P992-805-079-AY-GRV		\$	627.00
120	CLOSING ELEMENT PLATE	1	P992-805-597- Y-GRV		\$	349.30
121	ALLOY WHEEL TITANIUM	1	P992-601-025-H -OC6		\$	4,439.30
122	CROSS MEMBER	1	P992-401-309-J -		\$	2,877.90
123	HEXAGON-HEAD BOLT M 12 X 1.5 X 105 (WMA)	2	PPAF-008-757- -		\$	17.00
124	THREADED PIN	2	PPAF-008-737- -		\$	25.60
125	HEXAGON NUT M 12 X 1.5 (WMA8)	2	PN -909-167-01-		\$	15.40
126	HEXAGON-HEAD BOLT M 12 X 1.5 X 50 (WMA8)	2	PPAF-008-756- -		\$	25.60
127	TRAILING ARM LH	1	P992-407-325-F -		\$	800.10
128	HEXAGON BOLT	1	PPAF-008-970- -		\$	14.80
129	HEXAGON NUT M 14 X 1.5	1	PPAF-103-353- -		\$	7.20
130	WISHBONE LH	1	P992-407-151-E -		\$	1,188.70
131	HEXAGON-HEAD BOLT M 12 X 1.5 X 90	1	P9A7-008-209-00-		\$	13.60
132	HEXAGON NUT	1	PPAF-909-664- -		\$	4.30
133	LEVEL SENSOR LH	1	P992-616-213- -		\$	427.60
134	BRACE	1	P992-407-063- -		\$	55.90
135	ANGULAR CONTACT BEARING	1	P9P1-407-621- -		\$	288.60
136	SWIVEL MOUNTING LH	1	P992-407-245-AY-		\$	2,183.30

7	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET		NETT	\$ 150.00	✓
8	TO REMOVE & REPLACE TURBO COOLER, RADIATOR, CONDENSER AND RADIATOR FAN ASSY. (pl/21)		NETT	\$ 1,560.00	?
9	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.		NETT	\$ 500.00	✓
10	TO REMOVE & REPLACE THE FRONT UNDER CARRIAGE.		NETT	\$ 1,560.00	?
11	TO REMOVE & REPLACE FRONT CROSS MEMBER & STEERING RACK ASSY.		NETT	\$ 1,560.00	?
12	TO REMOVE & REPLACE THE DASH BOARD ASSY & ROOFLINING. 1560 X 1.5		NETT	\$ 3,120.00	2340
13	TO REMOVE & REPLACE THE AIR BAGS, AIR BAG ECU AND SEAT BELTS.		NETT	\$ 1,560.00	✓
14	TO REPLACE 1 PC TYRE. 245/35 R20		NETT	\$ 980.00	✓
15	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.		NETT	\$ 120.00	✓
16	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT	\$ 680.00	✓
17	TO REMOVE & REFIT THE FRONT WINDSCREEN GLASS.		NETT	\$ 560.00	✓
18	TO SUPPLY SEALER ON THE FRONT WINDSCREEN GLASS.		NETT	\$ 195.00	✓
19	TO SUPPLY SOLAR FLIM ON THE FRONT WINDSCREEN GLASS. (Sales agency)		NETT	\$ 300.00	?
20	TO INSTALL THE BODY WRAP STICKER. (PRICE TO BE ADVISE) (Sales agency)		NETT	\$ 350.00	?
21	TO TRANSFER THE FRONT BUMPER SENSORS.			\$ 500.00	200
22	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00	150
23	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$ 600.00	✓
24	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. (1040/12)		NETT	\$ 300.00	?
25	SUNDRIES.		NETT	\$ 50.00	20
		TOTAL LABOUR	\$ -	\$ 35,545.00	36445
		TOTAL PARTS	\$ -	\$ 108,230.60	
		TOTAL	\$ -	\$ 143,775.60	144675.60
		LESS EXCESS	\$ -	\$ -	
		TOTAL AFTER EXCESS	\$ -	\$ 143,775.60	
		GST 7%	\$ -	\$ 10,064.29	
		GRAND TOTAL	\$ -	\$ 153,839.89	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

137	SPACER PLATE LH	1	P9P1-407-115- -			\$	59.20
138	HEXAGON-HEAD BOLT	4	PN -108-063-01-			\$	8.00
139	SPEED SENSOR	1	P992-927-807- -			\$	258.60
140	PAN-HEAD SCREW	1	PN -105-464-03-			\$	3.20
141	WHEEL HUB LH	1	P9P1-407-615- -			\$	966.00
142	HEXAGON NUT	1	PWHT-007-021- -			\$	21.70
143	SHOCK ABSORBER LH	1	P992-413-031-E -			\$	1,939.00
144	DESK PAD	1	P9P1-412-149- -			\$	43.90
145	WASHER	1	P9P1-412-269- -			\$	35.00
146	THRUST RING	1	P992-412-253- -			\$	56.50
147	COMPENSATION RING	1	P992-412-377- -			\$	58.60
148	BEARING PLATE	1	P992-412-321- -			\$	230.20
149	HEXAGON NUT	2	PPAF-008-550-00-			\$	7.40
150	HEXAGON NUT (MS)	3	PPAF-003-923- -			\$	7.50
151	STABILISER MOUNTING LEFT	1	P9P1-411-317- -			\$	195.70
152	HEX. NUT (WMAS)	1	PPAF-007-957- -			\$	9.50
153	HEXAGON NUT	1	PPAF-909-664- -			\$	4.30
154	STEERING GEAR	1	P992-423-051-AL-			\$	9,222.00
155	HEXAGON COLLAR NUT SELF-LO	2	PPAF-908-088- -			\$	8.40
156	MAIN FUSE SOCKET	1	P992-937-619-A -			\$	108.30
157	ADHESIVE	1	PPAH-071-781-00-			\$	1,127.00
158	P999-190-229-01-/BLIND RIVET	70	PPAF-009-075- -			\$	392.00
159	POP RIVET	70	PPAF-912-885- -			\$	182.00
160		0	0			\$	-

TOTAL PARTS

\$ 108,230.60

TOTAL PARTS COST

\$ 108,230.60

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
Labour Description							
1	TO REMOVE /REPLACE BONNET, FRT BUMPER, FRT FENDER LH & RH, FRT LUGGAGE COMPARTMENT & ALL DAMAGED BODY PARTS. TO REPAIR FRONT DOOR RH & ALL AREAS AFFECTED BY THE ACCIDENT. 1560 X 7					10,920	\$ 12,480.00
2	TO RESPRAYB BONNET, FRT BUMPER, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT LUGGAGE COMPARTMENT & Door LH					7990	\$ 7,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.					250	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.					200	\$ 250.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT SECTION TO GIVE WAY TO THE REPAIR ON THE FRONT SECTION.					250	\$ 500.00
6	TO SUPPLY FRONT LICENCE PLATE WITH CASING					NETT	\$ 70.00

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Steve (LKK)

6/10/21, 12.30pm

OP- M L

EXPRS-?

P/P

M Bel sy

16 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/09/2021 18:06 (SGT)
Date of Accident	26/09/2021 11:30 (SGT)
Exact Location of Accident	Punggol, Aft Punggol Rd, TPE, Singapore
Additional Location Information	TAMPINES EXPRESSWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE17H
-----------------------------	--------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Teo Weixian
NRIC No	SXXXX574I
Email Address	club_17@live.com
Mobile Phone No	(Phone) +65-85550555
Alternative Phone No	+65-85550555

VEHICLE PARTICULARS

Manufacturer	Porsche
Model	911
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2981

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	TAN CHIN KHOON
NRIC No	SXXXX038G

Date Of Birth	24/03/1979
Occupation	Indoor
Date Of Driving Pass	03/02/1999
Driving experience	22 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91868299
Alt. Phone Number	-
Email Address	STEPHENTCK79@GMAIL.COM
Address	531 EAST COAST ROAD
Address complement	#05-03
Postcode	429065
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	SMA4E
Insurance Company of Other Vehicle Owned by Driver	China Taiping Insurance (Singapore) Pte. Ltd.

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	SERANGOON NPC
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

KINDLY REFER TO THE ATTACHED POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	RAILING
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Insurer's Signature
(If driver is not the policyholder)
Date & Time: 2017-07-17 14:30

Reporting Centre Personnel's Signature
Name:
Employee No.

SKETCH PLAN

car guided

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT		LICENSE PLATE NO.
ACCIDENT DATE:		CONTACT NUMBER
ACCIDENT TIME:		EMAIL:
LOCATION:		
N/A to police report Attached		
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAY TIME FRAME FOR YOU TO FURNISH AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY		
PLEASE CHECK YOUR POLICY FOR MORE INFORMATION		
PLEASE STATE	() CLAIM OWN POLICY	() CLAIM THIRD PARTY () REPORTING ONLY

DECLARATION

If We declare the foregoing particulars are true in every respect

Policyholder's signature _____
Date & Time: _____

Drop-off by:
(If driver is not the policyholder)
Date & time: 22/11/2020 @ 5

Responsible Officer Personnel's Signature
Name: _____
Date: 8/24/2015



SINGAPORE
POLICE FORCE



1/20210926/2008

1 of 1

Report No. 1/20210926/2008

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4860999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2021 20:56
Vide Report No.: G/20210926/0128
Station Diary No.: 36

Informant's Particulars

Name of Informant: TAN CHIN KHOON			Address: 531 EAST COAST ROAD #05-03 SINGAPORE 429085		
ID Type / ID No.: NRIC NO / S7909038G			Contact No.: Home/Office: Mobile: 91868299		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 42	Date of Birth: 24/03/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: DIRECTOR			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 26/09/2021 11:30	Type of Location: Straight Road
Location: TAMPINES EXPRESSWAY				
Weather: Heavy rain		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJE17H	Car					0

SINGAPORE
POLICE FORCE

112021002092068

2 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. 112021092062068

CONTINUATION OF REPORT

Brief Details.

On 26/09/2021 at about 1130hrs, I was driving my car SJE17H, along TPE towards PIE before Loyang Ave. I was driving at the extreme right lane when suddenly there was a sudden down pour of rain. Due to the sudden down pour, there was a puddle of water and as a result, I skidded and I hit onto the railing at the right and my car stopped.

20 minutes later, Ambulance and Traffic police came there after. I was fine and no injury. There was a dent to the railing and thus I was instructed to make a traffic accident report.

SINGAPORE
POLICE FORCE

T20210926/000

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No. 1800-4880999

3 of 3

Report No. T20210926/000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report 152
F /
Sgt 3 TEO JING XIAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/09/2021 20:56

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt SYED ZAYID MUHAMMAD BIN
SYED ABDUL WAHID ALHINDUAN
Contact No.: 65476404

Classification Of Case: