

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 23 Nov 2021

Preliminary Advice

Vehicle No	: SJE17H	Accident Date	: 26/09/2021
Make	: PORSCHE 911	Policy No.	: DMPCSNW00129022000
Assignment Date	: 05/10/2021	Excess	: S\$6,000.00
Date of Inspection	: 06/10/2021	Est. Duration of Repair	: 21
Inspection At	: STUTTGART AUTO PTE LTD 27A TANJONG PENJURU SINGAPORE 609042		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	151,245.50	(ESTIMATE \$144,675.60 + SUPPLEMENTARY \$6,569.90)
Revised Amount	:S\$	98,081.00	
Check Items (Estimated)	:S\$	47,520.70	
Total	:S\$	145,601.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	560,000.00
COE / PARF Rebate	:S\$	239,008.00
Salvage Value	:S\$	
Margin for Repair	:S\$	320,992.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.